ASS. REC. BY: COMM. REF: CCY LIC 27	200 6479 Rga3 907m
	SIGNMENT
From: Date:	Veh No: CB 7053 7 Yr Regn: 2017 1 MC
Estimated Cost:	Type: M.Car / M.Cycle Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: CB 7653E	Make: KINHLOWY (XMQ69WK c.c 6693
at Workshop m/s SC MWW	Colour PURPLE A/C: Insured / Std / NI / NA
of SI, Sanoko RD	Sp.Reading 674464 T/Radio: Insured / Std / NI / NA
Insured: LPC	Eng/No:
PolicyNo.	CINO: LAGRIDSB3BB 204041
Claims No.	Gen. Cond: Good Fair Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi : Nil / S/Rim / STD A/Rim or
(Policy Condition)	
Remark: The veh had commenced its N/S O/S	R: ~ ~ JND BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value: 32K	
IDAC Accident Rport: Consistent? : Yes or No	P/Rel Q D/Rel 6/6
GIA / PR Seen: Consistent?: Yes or No	1/8al 9 1/8al 0/0 mm
Est. Repairs: days Res.: Yes or No	DOA 28/10/22
Lum Sum: % 3 Val.: Yes or No	12/01/12
14일 :	
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The U/C / Chassis frame Body Structure affected due to collision
Date / Time Action / Instruction	The size of the si
reform limit - 32K	
te/Time, File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
le/Time, File Return to?	Transportation:
Add Fee	
그 보고 한다는 그리고 있었다. 그리고 생각했	Intention (C
그림, 그	
port Format :	: Tech. Invs (\$) Others

:Weekend (\$

TOTAL

SC AUTO

SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133 **T** 65 6758 2222 **F** 65 6257 6931 **E** sales@scauto.com.sg scauto.com.sg

Co. Reg. No. 199800107D

M/S

KW BUS SERVICE

Blk 764a, Woodlands Circle, #10-304,

SINGAPORE 731764

Insured

KW BUS SERVICE

Policy

DMB1SNW00012602004

ESTIMATE Bill

GST Reg. No:

19-9800107D

Date:

7/7/2022

Our Case Ref.

SC22/07/086/4KB-TP

Accident Date

7/7/2022

S/no	Description	QTY	Price	Disc	Amount
1	Replaced Parts SIDE MIRROR ASSYLH reprint	1 PC		-	\$1,980.00
	Labour Charges				e.
1	LABOUR TO CHECK WIRENESS.	1	\$650.00	. 300	\$650.00
2	LABOUR TO REMOVE, REPAIR AND REINSTALL SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY AND FRT BUMPER.	1	\$3,000.00	- (280	\$3,000.00
3	LABOUR TO RESPRAY SIDE MIRROR ASSY LH, FRT FIBER CAP ASSY, FRT BUMPER.	1	\$2,500.00	-960	\$650.00 \$3,000.00 \$2,500.00
4	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	\$250.00		\$250.00
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		Ross	e Sweet days Ip ize 14 after	

Sub Total

\$ 8,380.00

SS2P22720002 / SC Auto Industries Pte Ltd ENTRY DATE & TIME: 04/07/2022 11:07 (SGT) SUBMITTED BY: Hamimah Bte Jamaludin VERSION: 1 (04/07/2022 11:07 (SGT))

© SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/07/2022 11:07 (SGT) Reported by Driver Date of Accident 28/06/2022 18:50 (SGT) Exact Location of Accident 7 Elias Green, Singapore 519962 Additional Location Information ALONG TPE AFTER EXIT 3B Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **CB7053E** INSURED/POLICYHOLDER

Is company? Name Of Registered Owner K W BUS SERVICE Company Reg No 5XXXX907W Email Address OHSIAK71@GMAIL.COM Mobile Phone No (Phone) +65-93861674

Alternative Phone No

VEHICLE PARTICULARS

King Long XMQ6900K

Exact purpose for which vehicle was being used at time of accident **Employment**

Are you claiming under your own insurance policy for repair to No - Claiming third party Vehicle Category Bus

Transmission Manual 6693

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMB1SNW00016772105

DRIVER

Name of Driver ANDIN KHAIRULLAN ACHMAD NRIC No SXXXX234I Date Of Birth 07/08/1973 Occupation Outdoor

Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	05/05/2021 1 YEAR AND 1 MONTH Male (Phone) +65-87494631 - OHSIAK71@GMAIL.COM BLK 683A EDGEDALE PLAINS #09-715 821683 No Employee No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Major/Minor Rd Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name Gender	-
PASSENGER 2 Name Gender	UNKNOWN Male
PASSENGER 3 Name Gender	UNKNOWN Male
PASSENGER 4 Name Gender	UNKNOWN Male
PASSENGER 5 Name Gender	UNKNOWN Female
PASSENGER 6 Name Gender	UNKNOWN Male
PASSENGER 7 Name Gender	UNKNOWN Male
	Page 2 of 15

Fee

irtatio

Was the accident reported to the police? Was notice of intended Prosecution giver If yes, against whom?		0
200000000000000000000000000000000000000	-	
CIRCUMSTANCES OF ACCIDENT		

I WAS DRIVING ALONG TPE TOWARDS SLE. AFTER EXIT 3B, A LORRY 14FT YP5670C CUT INTO MY LANE . THE LORRY SIDE

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP5670C
Vehicle Manufacturer	11 30700
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	- (
\/-L:-L	-
Vehicle Category	Commercial vehicle
Name of Driver	_
Contact Number	_
Address	_
Address complement	-
Destroyde	-
	-
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	<u>-</u>
No. Of Passenger (Including Driver)	_
3 - 1.0.1	-

Irc

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My Insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

& Time

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of cartain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

Sketch Plan

1 PC

Describe	Circumstances	of	the, Acciden
		•	and, Acciden

I was dviving along the towards fully SLE, After Exit 3B, a Lovry 14ft YP 5670 C Cut the into my 1	
Exit 3B a Lovry Keft VP 5670 C and then the lines	
that The love side swine my love	an
The south my bus,	
'n	
·	
· · · · · · · · · · · · · · · · · · ·	
	_
	\dashv
	_
	\dashv
	\dashv
	\neg
	\neg
	\neg
	\neg
	_

Declaration

We declare the foregoing particulars are true in every respect.

TWO SENSON

Policyholder's Signature / Date & Time

· Dr

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

O. A. ID.	
Owner ID Type:	是是是有多少多多 Business 是是是是多多多的的形式中的影響的影響的影響的
Owner ID:	907W
Vehicle No.:	CB7053E
Vehicle to be Exported:	A B S S S S S S S No S S S S S S S S S S S
Intended Deregistration Date:	13 Jul 2022
Vehicle Make:	KINGLONG
Vehicle Model:	XMQ6900K
Primary Colour:	White The Control of
Manufacturing Year:	2011
Engine No.:	IS8E420522002096
Chassis No.:	LA6R1DSB3BB204041
Maximum Power Output:	TYPE VIZIONAL ARRESTATION OF THE RESIDENCE OF
Open Market Value:	\$99,404.00
Original Registration Date:	12 Dec 2012
First Registration Date:	12 Dec 2012
Transfer Count:	
Actual ARF Paid:	1
PARF Eligibility:	No. 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.0 0
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 13 Jul 2022

ОК