

Your Ref: SS/SM/2021001541.MSIG(MPD)

Date: 15th July 2022

Our Ref: CS1/LAW22006491/Dqy3e2

M/s Kelvin Chia Partnership6 Temasek Boulevard 29th
Floor Suntec Tower Four
Singapore 038986

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLN 2557G
INSURED VEHICLE: SDM 669E
ACCIDENT DATE: 02/02/2021**

We thank you for your instruction on 24/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLN 2557G from M/s MC-COY Appraiser Pte Ltd.
- b) Survey report by A-PAC Adjusters & Surveyors Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles SLN 2557G and SDM 669E.
- d) Police Report of Vehicles SLN 2557G.
- e) Colour damaged vehicle photographs of SLN 2557G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLN 2557G
Make & Model	: Honda Vezel
Chassis Number	: RU11206627
Year of Registration	: 2017
Engine Capacity	: 1496 cc

- 2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.