

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CCG/AIG 22006494/Upa3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: YN2725Jat Workshop m/s 1.1.5 30

of _____

Insured: SBA 8000T

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 36

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 196N

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 20873Veh No: YN2725J Yr Regn: 02/04/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or RefrigeratedMake: HINO X24700R c.c. 4009Colour: white A/C: Insured / Std / NI / NASp. Reading: 223 815 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHHTCP3H 70K001212Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 7.00 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Austone

Front

Rear

R/Bal. P mm R/Bal. 8/8 mmL/Bal. 8 mm L/Bal. 8/8 mmD.O.A. 02/07/22 D.O.I. 7/7/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &The U/C / Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction Dep 8k.No renew coe from SG cement
coe until 31-03-202719/1/22 M/S 2200 informed Suser.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)