OT:	Prio	rity: NORMAL	URGENT				
Reference No : 6	V ABS 2200650	& EcClaim No.		,	IN OPS : Yes I	No DOA:	
	Tane		ABS		Ref:		
Date/Time :	CEOS F 8				MV:S		
	1	Management Among					
TYPE: M.Car / M	l. Cycle / Bus / Van	/Lorry/Taxi/F	Prime Mover / Truck	(/ Trailer	or		
	GBJ 33640		_				
Make & Model:	000 000		disig	NEV	V CAR PRICE	\$	
			•			Quote by :	-
Registration Date:				FS:\$			-
COE Expiry Date:			. (005)			SV:\$	-
LIA Iotal Rebat	te Amount: (PA	ARF)	+ (COE)	=======================================		Ψ Ψ	
Calculation for	I TA Pohate:		Calculation fo	r Valuat	ion:		<u> </u>
	X 12 = _	Mths	Average MV	, valuat		\$	
As At:							
	•	= Mths	Calculation fo	r Repos	sessed vehic	le:	
	-	= Mths	- 1			- \$.,
(b) Balance Mo	nths:		Parallel Import	yehicle:	Yes / No	- \$	
			More than 10y			- \$	
(d) Residue COF :	$QP = \times \frac{(b)}{(a)}$		MV for Repo	ssessed	vehicle	= \$	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	(a)				,	1 0	
*		3	Engine Capac		High / Low	- \$	
)=_/12=		Europe / Asia		air/Poor/Burnt		<u> </u>
_	After MAY 2002			Car Condition: Good/Fair/Poor/Burnt No. of transfer:			
(e) PARF = (OMV) X =				No. of transfer: - \$ Other deduction - \$			
LTA Total Rebate Amount: (d)+(e)Salvage Value(LTA Rebate - 5%):			Forced Sales Value derived = \$				
	,.	***************************************					
Date / Time	Action / Instru	ıction	Additional Info	ormation:			
	GBT 3364D -7	Χ		-			
							
·							
		·					
*,							

Celine Fong (LKKAuto)

From:

jane@absfinancial.sg

Sent:

Tuesday, 5 July 2022 2:17 PM

To:

Celine Fong (LKKAuto)

Cc:

assignments; joanne@absfinancial.sg; 'AMBER'

Subject:

Inspect-GBJ3364D

Attachments:

GBJ3364D.pdf

Hi Celine,

I have attached log card for you to go inspect , Monday-Friday 9-5:30pm Address: 38M PENJURU RD

Thank you

Warmest Regards,

Jane

Admin Executive 38M Penjuru Road (S) 609148

T: 6933 9391 F: 6456 0678



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Duringer
Owner ID Type:	Business
Owner ID: Vehicle Details	440M
Vehicle No.:	GBJ3364D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Jul 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	T6 VAN TDI NWB DSG
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CXH179426
Chassis No.:	WV1ZZZ7HZKH031629
Maximum Power Output:	
Open Market Value:	\$29,796.00
Original Registration Date:	13 Mar 2019
First Registration Date:	13 Mar 2019
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$1,490.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	12 Mar 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,009.00
COE Rebate Amount:	\$17,868.00
Total Rebate Amount:	\$17,868.00
ne information contained herein is correct as at 05 Jul 2022	
	Das Pla.
	OK ~ / V
	76.
	OKDET Bl. 76. Sol 6 yrs. Imh.
	MV: \$6 Fs: 46
	il (
	Fe: 40

3A/11		
lainvalation.		

ł.	J	ь,	44	h	2

ASSIGNMENT

From: Date:	Veh No: GBJ 33640 Yr Regn: / J019				
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /				
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or				
To Inspect Vehicle No:	Make: VOLKSWAGEN T6. c.c 1968				
at Workshop m/s	Colour A/C: Insured / Std / NI / NA				
of -	Sp.Reading 10.5379 T/Radio: Insured / Std / NI / NA				
Insured:	Eng/No:				
Policy No.	CINO: WYIZZZTHZKHO31629				
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt				
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or				
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or				
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or				
	Tyre Size: F:				
(Policy Condition)	R:				
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /				
repair at the time of inspection.	TOYO/YOKO or				
Bal. or Market Value:	Front Rear				
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm				
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm L/Bal. mm				
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 6 7 2022				
Lum Sum: % 3 Val.: Yes or No	Survey held at Penjune Rd.				
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or				
Vehicle: IN / OUT					
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.				
Date / Time Action / Instruction	•				
Date/Time, File Pass to? : Preli. Report	Days Of Repair:				
1) : Final Report	Resurvey No. of Trip: Survey Fee:				
Date/Time, File Return to?	Transportation:				
2) Add Fee	: Site Insp (\$)_s+Rs,_s				
	: Interview (\$) Photos				
Report Format :	: Tech. Invs (\$) Others				
Lump Sum / I.B.I: (\$:Weekend (\$				
	TOTAL				