ASS. FEG. BY:				
-		ASSI	GNMENT	
From:	Date:		Veh No: SLW9360	6 Y. Yr Regn: 2018 / March
Estimated Cost:			Type: M.Car M.Cycle / Bus / Van	
OD / TP/WS / TP RES / OD RES / EVA / INV / MV			Truck / Trailer or	
To Inspect Vehicle No:			Make: Handai	Elevitra. C.C 1591
at Worlshop m/s			Colour Silver	A/C: Insured / Std / NI / NA
of			Sp.Reading 87505	T/Radio: Insured / Std / NI / NA
nsured			Eng/No:	
olicy No.				1cm Ju 645461
Claims No.			Gen. Cond: Good / Fair / Poor / Bu	
um Insured;	Excess:		Steering: Inorder / Jammed / Leak	
(Clien's Record)			Brake: injorder / Jammed / Leaked / Burnt or	
Make of Veh:			Modí: Nil /(S/Rim)/ STD A/Rim or	
(Section 1997)			Tyre Size: F: 205/	
(Policy Condition)			55R16	
Remark The veh had commenced its N/S O/S		BS / DUN / EXNOVA / GY / FS / LI		
repair at the time of inspection.			TOYO / YOKO or	
Bal. or Market Value:			Front	Rear
IDAC Accident Rport: Consistent? : Yes or No			R/Bal. mm	R/Bal. 06 mm
GIA / PR Seen: Consistent?: Yes or No			L/Bal. 06 mm	L/Bal. 06 mm
Est. Repairs: days Res.: Yes or No			D.O.A.	D.O.I. 08 07/22
um Sum:	% 3 Val.: Yes or	No .	'Survey held at	D Perfect.
CA / REV / REF	P. / 24 HRS		Des. of Damages : Frt / Rear / C	D/S / N/S / U/C / Rooftop or
Date:	Ve Person Contacted:	hicle: IN / OUT		
	tion / Instruction		The U/C / Chassis frame / E	Body Structure affected due to collision.
Date / Time Act	TP 111		f	
- Sec. 1				Survivo Sur
mv		•		
PV			-	
Net	<u>† : </u>			trial switches us
			an in the little	
ate/Time, File Pass to?	: Preli. Report		Days Of Repair:	
	: Final Report		Resurvey No. of Trip:	Survey Fee:
Date/Time, File Return to?			Transportation:	
2) Add Fee			: Site Insp (\$)6+R66'
			: Interview (\$) Photos
Report Formet:			: Tech. Invs (\$) Owers

SK0N22780004 / KAN FOOK SING MOTOR WORKSHOP [539147] ENTRY DATE & TIME: 08/07/2022 12:13 (SGT) SUBMITTED BY: DARRELL LEK VERSION: 1 (08/07/2022 12:13 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver

Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/07/2022 12:13 (SGT) Reported by Date of Accident 07/07/2022 18:30 (SGT) **Exact Location of Accident** Singapore Additional Location Information SLE(CTE/TPE) BEFORE WOODLANDS AVE 2 EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW9366Y

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner PANEARSELVAN S/O VEERAPPAN NRIC No S1328357E **Email Address** VIPSELVAN@GMAIL.COM Mobile Phone No (Phone) +65-97982831 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Hyundai Model Elantra Variant Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

INSURANCE COMPANY

Name of Insurance Company Great Eastern General Insurance Limited Policy Number / Cover Note Number V5001715

DRIVER

CC

Name of Driver NRIC No Date Of Birth Occupation

PANEARSELVAN S/O VEERAPPAN S1328357E 12/03/1958 Indoor

No - Claiming third party

Private car

Auto

1591

Date Of Driving Pass 08/03/1984 Driving experience 38 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-97982831 Alt. Phone Number **Email Address** VIPSELVAN@GMAIL.COM Address 749 WOODLANDS CIRCLE #07-602 S730749 Address complement Postcode Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email

PASSENGER 1

Name LALITHA
Gender Female

DETAILS OF POLICE ACTION

Original language used in the statement

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED REPORT

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender	PANEARSELVAN S/O VEERAPPAN Male
Phone No	(Phone) +65-97982831
Address	-
Address Complement	
Post Code	
Approximate Age Years Old	•
Injuries Sustained	
Injured person in which vehicle?	SLW9366Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

INJURED 2

INJUNED Z	
Name of injured person	LALITHA
Gender	Female
Phone No	(Phone) +65-97982831
Address	
Address Complement	-
Post Code	-
Approximate Age Years Old	
Injuries Sustained	-
Injured person in which vehicle?	SLW9366Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GN Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

& Time

- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &


Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel LEK SILL ENG

Sketch Plan

Vch A: SLW 9366 Y uch B'. SM 05394L





Declaration

I'We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date 8 Time

Witnessed by Reporting Centre Personnel LEK SILL ENG

ON THE STATED DATE AND TIME. I, VEHICLE A (SLW9366Y)
WAS TRAVELLING STRAIGHT ON LANE 1 OF SLE(CTE/TPE)
BEFORE WOODLANDS AVENUE 2 EXIT. WHEN THE FRONT
VEHICLE SLOWED DOWN AND STOP, I FOLLOWED SUIT TO
SLOWED DOWN WITHOUT HAVING ANY COLLISION WITH
THE FRONT VEHICLE. SUDDENLY I FELT A HUGE IMPACT
FROM THE REAR PORTION OF MY VEHICLE. AFTER I ALIGHTED
I THEN REALISE THAT IS VEHICLE B (SMQ5394L) THAT HAD
COLLIDED ONTO MY VEHICLE.

I WISH TO STATE THAT I GOT 1 PASSENGER IN MY CAR.

VEHICLE A: SLW9366Y VEHICLE B: SMQ5394L

