

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 199607	198R GST Reg. No. 19-	-960/198-R	
		Affiliated to Federation Internation	nale Des Experts En Au	tomobile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef: CS/AGI22006536/Ucy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate: 05/08/2022	
			Co	ode: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLW 8762T	Veh. Inspected	SMA 72H	
	Policy No.	P10327415R02	Coverage (\$)	0.00	
	Claim No.	C10016239/JT	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	08/07/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1332	
	Engine No.	HIDDEN	Year of Reg.	2021	
	Chassis No.	W1K1183842N219794	Colour	WHITE	
	Odometer	19432 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	245/30Z R20	MICHELIN	7 mm	
	L/H Front Tyre	245/30Z R20	MICHELIN	7 mm	
	R/H Rear Tyre	245/30Z R20	MICHELIN	7 mm	
	L/H Rear Tyre	245/30Z R20	MICHELIN	7 mm	
4.	Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
	DAMAGES SEE D	ETAILS.			
5.	General Information				
	Accident Date	06/07/2022	Inspection Date	08/07/2022	
	Survey held at	ZOOM AUTOWERKS PTE LTD			
	130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130				
5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)III / IOOORDAIN	Estimate Days of Repair			
	Louinate Days of Nepall				

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: