



Your Ref: 22.29835

Date: 26th July 2022

Our Ref: CS3/ASM21003357/Eqy3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GX 9486M

INSURED VEHICLE: SHA 4406L

ACCIDENT DATE: 07/03/2021

We thank you for your instruction on 06/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GX 9486M from M/s Precision Appraisal Services.
- b) Singapore Accident Statement of Vehicles GX 9486M and SHA 4406L
- c) Final Repair Bill of GX 9486M from M/s Hong San Hong Wei Pte Ltd.
- d) Colour damaged vehicle photographs of GX 9486M.

Pre-Repair Inspection Date: 16/03/2021 at M/s Hong San Hong Wei Pte Ltd, 1002 Bukit Merah Lane 3 #01-85 Alexandra Village Ind'l Est, Singapore 159719.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GX 9486M
Make & Model	: Peugeot Partner1.9DM
Year of Registration	: 2004
Chassis Number	: VF3GCWJYB96105901
Engine Capacity	: 1868 cc

2. We recommend that the repairs of the entire damage require about 7 (Seven) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.