

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7162D

Date: 28/06/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 35.60
1	REAR BUMPER REFLECTOR LAMP RH			\$ 32.00
1	REAR BUMPER LOWER COVER			\$ 228.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
1	RR BUMPER REINFORCEMENT BRACKET RH			\$ 160.60
	SUB TOTAL			\$ 1,459.60
	LESS 20%			\$ 291.92
	DISCOUNTED TOTAL			\$ 1,167.68
	Labour Charge			
	PANEL BEATING			\$ 320.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/ REFIX EXHAUST PIPE			\$ 150.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 830.00
	ESTIMATE TOTAL			\$ 1,997.68

de-
ner-
X
X
X
?
?

Nett
280
250
X
30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495749
 up 28/6/22 @ 430pm
 2 days
 Lbs rising after repair
 Tanpin @ 11th and 12th

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4327350

JC NO305521346

CUSTOMER

MR/MS **COMFORT TRANSPORTATION PTE LTD**
CUSTOMER NO. **7010045**
ADDRESS **383 SIN MING DRIVE**
Singapore SINGAPORE 575717
TEL. (R) **65508755** (O)
(P)

REGN NO: **SHD7162D**

MILEAGE

MAKE: **HYUNDAI**

FUEL

MODEL **I-40**

E.....1/2.....
DATE/TIME IN **28.06.2022 08:15**

YR OF MANU. **17.11.2016**

TARGET DATE

CHASSIS CODE **KMHLB41UMHU096367**


COMPLETION DATE/TIN

DISCOUNT CARD NO.

Accident Date: 27.06.2022
NATURE: 3P 27.06.2022

JOB DESCRIPTION

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHD7162D** **YY**

Vehicle No.: **SHD7162D**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard