

ASS. REC. BY: Taufik

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB6637TYr Regn: 249 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundaic.c. 1580Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 324/40

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HC851CVK U164748Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wanflube

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 30/6/22Survey held at Comfort Lorry

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP-INC-GBD64914

Taufik finalised LS \$1550, 2 days. (Red \$3918.78, 72%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Format: TPLump Sum / 1550

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 30.06.2022
Time: 15:35:45
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305521715
REGN NO : SHB6637T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 30.06.2022 10:20
ACCIDENT DATE : 29.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT


PART REQUISITION

0001 04-01-0104-0574-G	PANEL-FENDER LH#	1	588.80	20.00	471.04	60
0002 04-01-0104-2573-G	COVER-FR DR O/S HDL LH	1	234.80	20.00	187.84	aut
0003 04-01-0104-0593-G	PANEL ASSY-FRONT DOOR LH#	1	1,797.20	20.00	1,437.76	Rx
0004 04-01-0104-3813-G	EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28	rel
0005 04-01-0104-0600-G	MIRROR ASSY-OUTSIDE RR V	1	1,391.70	20.00	1,113.36	Rx
0006 28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	rel

SUB-TOTAL : 3,298.78

JOB NATURE

0000 PB	PANEL BEATING	900.00	525
0001 SP	SPRAYPAINT CHARGE	900.00	750
0002 17-01	CHECK ALL LIGHTING	50.00	X
0003 L	TRANSFER DOOR PART	120.00	X
0004 20-05	ADVERTISMENT STICKER-FENDER	100.00	aut



Date/Time: 30.06.2022 15:14

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4344831

JC NO305521715

OMER

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

DUNT CARD NO.

REGN NO.:

SHB6637T

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 30.06.2022 10:20

YR OF MANU.

24.07.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164748

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 29.06.2022

ATURE: 3P 29.06.22

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHB6637T

JU NTUC

Vehicle No.:

SHB6637T

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard