

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

INC

Date: 30.06.2022
Time: 15:35:45
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305521715
REGN NO : SHB6637T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 30.06.2022 10:20
ACCIDENT DATE : 29.06.2022

JOB / PARTS DESCRIPTION


QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0574-G	PANEL-FENDER LH#	1	588.80	20.00	471.04	66
0002 04-01-0104-2573-G	COVER-FR DR O/S HDL LH	1	234.80	20.00	187.84	aut
0003 04-01-0104-0593-G	PANEL ASSY-FRONT DOOR LH#	1	1,797.20	20.00	1,437.76	Rx
0004 04-01-0104-3813-G	EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28	rel
0005 04-01-0104-0600-G	MIRROR ASSY-OUTSIDE RR V	1	1,391.70	20.00	1,113.36	Rx 25% 680 ilb
0006 28-01-0103-0003-A	FRT DOOR LOGO CTPL	1 N	75.00	10.00	67.50	rel 75 10% 67.50
SUB-TOTAL :						3,298.78

JOB NATURE

0000 PB	PANEL BEATING	900.00	S25
0001 SP	SPRAYPAINT CHARGE	900.00	500
0002 17-01	CHECK ALL LIGHTING	50.00	X 111
0003 L	TRANSFER DOOR PART	120.00	X 111
0004 20-05	ADVERTISEMENT STICKER-FENDER	100.00	aut



REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305521715
REGN NO : SHB6637T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 24.07.2019
DATE/TIME IN : 30.06.2022 10:2
ACCIDENT DATE : 29.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0005 20-05 ADVERTISEMENT STICKER-DOOR

100.00 *ant* 1225

SUB-TOTAL : 2,170.00

TOTAL : 5,468.78

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanphir 97495749
WP' 30/6/22 @ 330pm
cls Rising after repair
Tanphir @ Lkh auto. now
21 days.

680.16
67.50
1225
1972.66
4581550
2 days

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: