

INVOICE
 6553
 MAHA Y15ZR
 UG0520L01148
 /20
 -31
 Price - SGD

NTUC - L/SUM
 Date: 30.06.2022
 Time: 09:28:47
 Page: 1

COMFORTDELGRO ENGINEERING PTE LTD
 REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305521605
 REGN NO : SHC1862L
 MILEAGE : 000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 30.06.2022 08:10
 ACCIDENT DATE : 30.06.2022

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	de
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	one
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	net
0004	04-01-0104-2544-G	CAP-RR HOOK	1	98.80	20.00	79.04	x un
0005	04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1	55.80	20.00	44.64	2 un 20% = 746.12
0006	04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16	k un SN 50.
0007	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00	50.00	all

SUB-TOTAL : 952.96

JOB NATURE

0000	PB	PANEL BEATING		400.00		350
0001	SP	SPRAYPAINT CHARGE		300.00		250
0002	L	REMOVE/REFIX REVERSE SENSOR		50.00		30
0003	20-05	ADVERTISEMENT STICKER-FENDER		200.00		net - L/S \$1300 2 days

Tan Jia 97495749
 'WP' 30/6/22 @ 3pm
 L/S Money after repair
 @ 2 days
 Tan Jia @ the auto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: