

ASS. REC. BY: Taufik

REF:

NS/ INC 22006559/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBF 1817Z**

Policy No. _____

Claims No. **MT/1178127-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<u>X</u>	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Wahid

Vehicle: IN / OUT

Veh No: SHA 6980G Yr Regn: 2019, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Wong C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 343650 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH085/CVCH/164378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 175

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wan Hui

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/6/2022 D.O.I. 24/6/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/8/22 Taufik informed LS \$800 (Red 1461.48, 64%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2) 17/8/22-typist

Rep. Format: TP

Lump Sum / L.S. / \$800

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA6980G

Date: 24.06.2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			Rx \$459.40
10	REAR BUMPER CLIPS			re - \$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			de - \$451.25
1	REAR BUMPER REINFORCEMENT			? \$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH			? \$138.10
1	REAR BUMPER TOWING COVER			X \$98.80
	SUB TOTAL			\$1,564.35
	LESS 20%			\$312.87
	DISCOUNTED TOTAL			\$1,251.48
	REAR BUMPER RUBBER MAT			Rx \$50.00
	REAR BUMPER REVERSE SENSOR			? \$180.00
				\$230.00
	Labour Charge			
	PANEL BEATING			\$50 \$400.00
	SPRAY PAINTING CHARGE			250 \$300.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$780.00
	ESTIMATE TOTAL			\$2,261.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphin 97445749
 up' 24/6/22 @ 3pm
 2 days
 c/s resurvey after repair
 tanphin c/ltk auto wq

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 24.06.2022 08:24

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4299122

JC NO 305520757


CUSTOMER		REGN NO.: SHA6980G	MILEAGE
MR/MS	COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
CUSTOMER NO.	7010045	MODEL IONIQ(G2)	DATE/TIME IN 23.06.2022 14:05
ADDRESS	383 SIN MING DRIVE Singapore SINGAPORE 575717	YR OF MANU. 26.06.2019	TARGET DATE
TEL. (R)	65508755	CHASSIS CODE KMHC851CVKU164378	COMPLETION DATE/TIME:
(P)	(O)		
DISCOUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 23.06.2022

NATURE: 3P 23.06.2022

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledgegement Slip

Exit Pass

me:

No.:

Vehicle No.:

SHA6980G

YY

Vehicle No.:

SHA6980G

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

be returned to Service Reception upon collection

To be kept by Security Guard