

Service Request Details

Claim	S2M0465M
Reference	CS3/ASM22006567/Vqy3m4 
Loss Date	5 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	7 Jul 2022 11:00:23 AM
Request Date	12 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information	
Incident	GBH5151Z
Vehicle	
Registration #	
Make	TPVD
Model	Toyota
Service Address	
, , ,	
Primary Contact/Insured	

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP PDF.pdf.pdf	Other	Other	do not reply	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2205271.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	26 August 2022
 AXA Immediate Advice - GBH5151Z (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 August 2022
 GBH5151Z TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	12 July 2022
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	12 July 2022
 SURVEY LIST.msg.msg	Legal	Others	KUMAR Shailendra	12 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	12 July 2022
 SJ0G2275000O-SHC1589B.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	7 July 2022