SG0G227E0004 / GOLDBELL ENGINEERING PTE LTD ENTRY DATE & TIME: 14/07/2022 15:51 (SGT) SUBMITTED BY: Kon Yin Siew VERSION: 1 (14/07/2022 15:51 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 14/07/2022 15:51 (SGT) Reported by Date of Accident 08/07/2022 08:40 (SGT) Exact Location of Accident Simei Ave, Singapore Additional Location Information BETWEEN LAMP POST 31A & 32A Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBJ8695R**

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner MR M&E PTE LTD Company Reg No 201304043D Email Address MURU.MRMNE@GMAIL.COM Mobile Phone No (Phone) +65-96455696 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Nissan Model Nv350 Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Commercial vehicle Transmission Auto 2488

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMCVSNW00109292100

DRIVER

Name of Driver **RENGASAMY ANANDAN** Work Permit No G8408617M Date Of Birth 15/05/1988 Occupation Outdoor

Diving experience Garder Mobile Number Mobile Number Mobile Number Promote 16-5-8266814 All, Phone Number	Date Of Driving Pass	24/09/2019
Mobile Number AL Phone Number Final Address AL Phone Number Final Address Address S037 ANG MO KIO IND PARK 2 701-377 Postcode 540599 Is the driver the policyholder? In No. Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles Owned by Driver Insurance Company of Other Vehicle O	Driving experience	2 YEARS AND 10 MONTHS
ALE Phone Number Email Address	Gender	Male
Email Address OFFICE MRNNE@GAMALL COM SAddress complement 901-377 Postcode 540569 Sted diver the policyholder? No Employee No	Mobile Number	(Phone) +65-82668614
Address complement #01-377 Postcode 540569 Is the driver the policyholder? No	Alt. Phone Number	_
Address (S037 ANG MO KIÓ IND PARK 2 ended to the policy of the policy holder? Postcode (S058) Side SWipe (S058) Side SW	Email Address	OFFICE.MRMNE@GMAIL.COM
Postcode site driver the policyholder? No No If No. Relationship of the Driver with the insured Does Driver Con Other Vehicles? No No If No. Relationship of the Driver with the insured No	Address	
Is the driver the policyholder? INO. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver CENERAL INFORMATION OF THE ACCIDENT Type of Accident Veather Conditions Road Surface OTHER INFORMATION Was any foreign vehicle involved in the accident? Was any foreign vehicle involved in the accident Vas any injured conveyed to hospital by ambulance? Vas any injured conveyed to hospital by ambulance? Vas any injured conveyed to hospital by ambulance? Vas any injured or Passengers (Including Driver) All States the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's ande Translator's Brone number Translator's Brone number Translator's Brone number PASSENMEER I NAMP BONE DETAILS OF POLICE ACTION Vehicle Registration Number ATTACHMENT(S) Are accident reported to the police? Was notice of intended Prosecution given? Vehicle Rodel Vehicle Registration Number Vehicle Registration Number Vehicle Registration Number Vehicle Model Vehicle Registration Number Vehicle Model Vehicle Model - Vehicle Registration Number Vehicle Model Vehicle Model - Vehicle Registration Number Vehicle Model - Veh	Address complement	#01-377
Is the driver the policyholder? INO. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver CENERAL INFORMATION OF THE ACCIDENT Type of Accident Type of Accident Vesting Conditions Road Surface Clear Dity CHERTINE-ORNATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident? No Number of vehicles involved in the accident No Was any highred conveyed to hospital by ambulance? No Was any highred conveyed to hospital by ambulance? Vess any highred to expery damaged? Yes Number of Passengers (Including Driver) Soliciting/offering accident claims assistance? Translator's name 1- Translator's mame 1- Translator's mame 1- Translator's mame NAVANEETHA KRISHNAN Make DETAILS OF POLICE ACTION Was the accident reported to the police? No No CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF FOLICE REGISTATION Vehicle Registration Number Schilde Registration Number Vehicle Model Vehicle Registration Number Vehicle Model - Vehicle Registration Number Vehicle Model - Vehicle Registration Number Vehicle Model - Vehicle Model	Postcode	540569
If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicle? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Road Surface Dity OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of Vehicles involved in the accident? Was any foreign vehicle involved in the accident? No Was any foreign vehicle involved in the accident? Was any injured or the Accident? Was any other vehicle or property damaged? Yes No Was any injured accident claims assistance? - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Is the driver the policyholder?	
Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Yea Accident Type of Accident Was any foreign vehicle involved in the accident? Was any plujured on the Accident? No Was any plujured on the Accident? No Was any plujured on the Accident? No Tanslator of Passengers (Including Driver) Last the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's ID Translator's ID Translator's phone number		
Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver CEHERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of Vehicles involved in the accident? No Was any foreign vehicle involved in the accident? No Was any foreign vehicle involved in the accident? No Was any foreign vehicle involved in the accident? No Was any injured on the Accident? No Was any injured on the Accident? No Was any injured on the Accident? No Was any injured conveyed to hospital by ambulance? - Was any of Personal Conveyed to hospital by ambulance? - Was any of Personal Conveyed to hospital Dy ambulance? - Was any injured accident claims assistance? No Was any injured accident claims assistance? No Translator's name		• •
Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Clear Conditions Clear Conditions Clear Control Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any injured on everyed to hospital by ambulance? Was any injured on everyed to hospital by ambulance? Ves any injured one-vehicle or properly damaged? Ves any one-vehicle or properly damaged? Ves (Including Driver) 2 Has the drive been approached by unknown persons) Soliciting/offering accident claims assistance? No Translator's Inno Translator's phone number Translator's phone number Translator's phone number Translator's email Original language used in the statement DeTAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Ves was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Model SHD4264M Vehicle Model SHD4264M Vehicle Model SHD4264M		110
CENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No No Number of Vehicles involved in the accident 2 Was any photy on the Accident? No No No Number of Passengers (Inciding Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name 1- Translator's phone number 1- Translator's phone number 1- Translator's phone number 1- Translator's email Original language used in the statement PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Vehicle Model 1- Vehicle Manufacturer Vehicle Model 1- Venice Model 1- Ve	Tomato Hogica auton Tumbor of Canon Tomato Cambrida Di Princi	-
CENERAL INFORMATION OF THE ACCIDENT Type of Accident Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No No Number of Vehicles involved in the accident 2 Was any photy on the Accident? No No No Number of Passengers (Inciding Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name 1- Translator's phone number 1- Translator's phone number 1- Translator's phone number 1- Translator's email Original language used in the statement PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Vehicle Model 1- Vehicle Manufacturer Vehicle Model 1- Venice Model 1- Ve	Insurance Company of Other Vehicle Owned by Driver	-
Type of Accident Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any othiquired in the Accident? No Was any other vehicle or property damaged? Was notice of intended Prosecution given? No DETAILS OF POLICE ACTION Was the accident reported to the police? No GIFURDINATANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT[S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF FOTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Model	, ,	
Type of Accident Weather Conditions Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any othiquired in the Accident? No Was any other vehicle or property damaged? Was notice of intended Prosecution given? No DETAILS OF POLICE ACTION Was the accident reported to the police? No GIFURDINATANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT[S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF FOTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Model	OFNEDAL INFORMATION OF THE ACCIDENT	
Weather Conditions Clear Road Surface Dry CTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any injured or never vehicle or property damaged? No Was any injured to the Accident? No Was any injured conveyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - No Was any injured orneyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - No Was any the vehicle or property damaged? Yes No Was any injured to the vehicle or property damaged? Yes No Was any injured orneyed to hospital by ambulance? No Was any injured orneyed to hospital by ambulance? No Was any injured orneyed to hospital by ambulance? No Was the accident experted by unknown person(s) Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(s) ATRACHMENT(s) DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Model - Vehicle Manufacturer Vehicle Manufacturer Vehicle Manufacturer Vehicle Model -	GENERAL INFORMATION OF THE ACCIDENT	
Weather Conditions Clear Road Surface Dry CTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any injured or never vehicle or property damaged? No Was any injured to the Accident? No Was any injured conveyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - No Was any injured orneyed to hospital by ambulance? - Was any injured orneyed to hospital by ambulance? - No Was any the vehicle or property damaged? Yes No Was any injured to the vehicle or property damaged? Yes No Was any injured orneyed to hospital by ambulance? No Was any injured orneyed to hospital by ambulance? No Was any injured orneyed to hospital by ambulance? No Was the accident experted by unknown person(s) Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(s) ATRACHMENT(s) DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Model - Vehicle Manufacturer Vehicle Manufacturer Vehicle Manufacturer Vehicle Model -		
Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No No Number of vehicles involved in the accident 2 Was any solved on the accident 2 Was any solved on the socident? No Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's Insame - Translator's Insame - Translator's phone number - Translator's phone number - Translator's email - Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufacturer Vehicle Model -	Type of Accident	Side Swipe
Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name - Translator's name - Translator's email - Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufacturer Vehicle Manufacturer Vehicle Manufacturer - Vehicle Manufacturer - Vehicle Manufacturer - Vehicle Manufacturer - Vehicle Model -	Weather Conditions	Clear
Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Yes Number of Passengers (Including Driver) 12 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's ID - Translator's ID - Translator's PID - Translator's email Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIPICUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Medel -	Road Surface	Dry
Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Yes Number of Passengers (Including Driver) 12 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's ID - Translator's ID - Translator's PID - Translator's email Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIPICUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Medel -		,
Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any injured conveyed to hospital by ambulance? - Yes Number of Passengers (Including Driver) 12 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's ID - Translator's ID - Translator's PID - Translator's email Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIPICUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Medel -	OTHER INFORMATION	
Number of vehicles involved in the accident 2 Was any body injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Was any other vehicle or property damaged? Yes Was any other vehicle or property damaged? Yes Was the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name - Translator's name - Translator's ID - Translator's phone number - Translator's phone number - Translator's person in the statement - Translator's person in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufacturer Vehicle Manufacturer - Vehicle Manufactur	OTHER INFORMATION	
Number of vehicles involved in the accident 2 Was any body injured in the Accident? No Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Was any other vehicle or property damaged? Yes Was any other vehicle or property damaged? Yes Was the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name - Translator's name - Translator's ID - Translator's phone number - Translator's phone number - Translator's person in the statement - Translator's person in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufacturer Vehicle Manufacturer - Vehicle Manufactur		
Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? - Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 12		No
Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 12 Has the driver been approached by unknown person(s) Soliciting/offering accident claims assistance? No Translator's name 1- Translator's name 2- Translator's phone number 3- Translator's email 1- Original language used in the statement 2- PASSENGER 1 NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufacturer - Vehicle Manufacturer - Vehicle Model SHD4264M Vehicle Manufacturer Vehicle Model Vehicle Manufacturer		2
Was any other vehicle or property damaged? Number of Passengers (Including Driver) 18st the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No 1-1	Was anybody injured in the Accident?	No
Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER I Name NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Manufactur	Was any injured conveyed to hospital by ambulance?	-
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's ID Translator's Ponen number Translator's Ponen number Translator's Ponen number Translator's email Original language used in the statement PASSENGER 1 Name MAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Registration Number Vehicle Manufacturer Vehicle Manufacturer Vehicle Model No No No No PASSENGER 1 No No No PASSENGER 1 No No PASSENGER 1 No No PASSENGER 1 No No PASSENGER 1 PASSENGER 1 No PASSENGER 1 PASSENGER	Was any other vehicle or property damaged?	Yes
soliciting/offering accident claims assistance? Iranslator's name Iranslator's phone number Iranslator's phone number Iranslator's phone number Iranslator's email Original language used in the statement PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model - SHD4264M Vehicle Model - SHD4264M Vehicle Model	Number of Passengers (Including Driver)	2
soliciting/offering accident claims assistance? Iranslator's name Iranslator's phone number Iranslator's phone number Iranslator's phone number Iranslator's email Original language used in the statement PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model - SHD4264M Vehicle Model - SHD4264M Vehicle Model	Has the driver been approached by unknown person(s)	
Translator's ID	soliciting/offering accident claims assistance?	No
Translator's phone number Translator's email - Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Manufacturer - Vehicle Model - Vehicle Manufacturer Vehicle Model -	Translator's name	-
Translator's email Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer Vehicle Model	Translator's ID	-
Translator's email Original language used in the statement - PASSENGER 1 Name NAVANEETHA KRISHNAN Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer Vehicle Model	Translator's phone number	-
Original language used in the statement PASSENGER 1 Name		_
PASSENGER 1 Name		_
Name		
Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	PASSENGER 1	
Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? - CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	Name	NAVANEETHA KRISHNAN
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Vehicle Registration Number Vehicle Manufacturer Vehicle Manufacturer Vehicle Model SHD4264M Vehicle Model		
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Vehicle Registration Number Vehicle Manufacturer Vehicle Model SHD4264M Vehicle Model -	dolidoi	Wale
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Was there any video captured by Car Camera? Vehicle Registration Number Vehicle Manufacturer Vehicle Model SHD4264M Vehicle Model -		
Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	DETAILS OF POLICE ACTION	
Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -		
If yes, against whom?	Was the accident reported to the police?	No
CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	Was notice of intended Prosecution given?	No
REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	If yes, against whom?	-
REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -		
REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	CIDCLIMETANCES OF ACCIDENT	
ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	CIRCUMSTANCES OF ACCIDENT	
ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -		
Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Manufacturer Vehicle Model SHD4264M - Vehicle Model	REFER TO SKETCH PLAN	
Are accident photos available for attachment? Was there any video captured by Car Camera? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number Vehicle Manufacturer Vehicle Model SHD4264M - Vehicle Model		
Was there any video captured by Car Camera? DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	ATTACHMENT(S)	
Was there any video captured by Car Camera? DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -		
Was there any video captured by Car Camera? DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	Are accident photos available for attachment?	Vos
DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	•	
Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -	The alore any ridge captured by Our Cumora:	INU
Vehicle Registration Number SHD4264M Vehicle Manufacturer - Vehicle Model -		A VELUCI E PROPERTO (
Vehicle Manufacturer - Vehicle Model -	DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Manufacturer - Vehicle Model -		
Vehicle Manufacturer - Vehicle Model -	Vehicle Registration Number	SHD4264M
Vehicle Model		_
	Vehicle Model	_
		-

Vehicle Colour Vehicle Category	- Taxi
Name of Driver	-
Contact Number	_
Address	_
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law-firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Persona Internation may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including that lawyershaw firms), which may be sited outside of Singapore, for one or more of the above Purposes

9.30am Policyholder's Signature / Date & Time


. Rég.No. 2013040430

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Kon Yin Siew

Sketch Plan



GB 3 8695R Vec 13: SHD4264M

scribe Circumstance of the Accident on 08/07/2022 @ 8:40 am
My driver was travelling along Gimei Are to
cilin Ave,
He planned to change temp bus lang
and turn on Indicating light and move to
with tide of the land Unfortunated car no B
the planned to Change tome bus lane and turn on Indicating light and move to might side of the lane. Unfortunatly car no B (SHD 4264M) and out van (GBJ 8695R) Collistin
be Side by Side.
Potta vertiles also donnel lide to side
Both rechiles also damaged side by side.
Taxi driver ask my driver to d. repair togond
our van and he managed to repair his taxi by
Us own. Ad And he never give his driving licence and Contact na als
that's why my driver never Submit report after
accident. But, we received the claim letter from
3H042bym on 13/07/2022.
So, we would like to submit our report and
also claim for our own danage too.
(Owner/In-charge/Driver) Seliah Mungon, NRIC NO: S7664332F Vehicle No: GB 38695
vill be sending my above stated damaged vehicle to Company name:
or my vehicle damaged repairs and insurance claims.
BBE had clearly informed me on new GIA rules. I accepted all liabilities and discharge Goldbell
ngineering Pte Ltd.
Declaration WE P
I/We declare the foregoing particulars are true in every respect.
An Yin Siew
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Alori 200 mm P. Am 14/09/2022
Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date Name as in NRIC/ID card)













