# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 08/07/2022 17:15 (SGT) Reported by Date of Accident 07/07/2022 09:15 (SGT) Exact Location of Accident AYE, Singapore Additional Location Information Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number XD7917D

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner SHANGHAI TUNNEL ENGINEERING CO (S) PTE LTD Company Reg No 199606990H Email Address ryderautoworkshop@gmail.com Mobile Phone No (Phone) +65-81689448 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Hino Model FS1ETLA-KAS Variant Exact purpose for which vehicle was being used at time of accident **Employment** 

Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Commercial vehicle Transmission Manual CC 12913

**INSURANCE COMPANY** 

Name of Insurance Company ERGO Insurance Pte. Ltd. Policy Number / Cover Note Number DMCG22000896

DRIVER

Name of Driver **BAN YONG HOE** NRIC No S7568025B Date Of Birth 09/03/1975 Occupation Outdoor

Date Of Driving Pass	24/04/2009
Driving experience	13 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81689448
Alt. Phone Number	-
Email Address	ryderautoworkshop@gmail.com
Address	10 PASIR RIS LINK #07-40
Address complement	TO FACILITIES EINIX #07-40
Postcode	- 518163
Is the driver the policyholder?	
	No
If No, Relationship of the Driver with the Insured  Does Driver Own Other Vehicles?	Employee
	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	-
insurance company of other vehicle owned by briver	-
OF MEDIA INCORPATION OF THE ADDITION	
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry
	ыу
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	
Translator's phone number	
Translator's email	
Original language used in the statement	-
PASSENGER 1	
Name	UNKNOWN
Gender	Male
DAGGENGED 6	
PASSENGER 2	
Name	UNKNOWN
Gender	Male
DETAIL C OF POLICE ACTION	
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	Yes
Police Station Name	Bedok South Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002448999
Alt. Police Station Phone No	·
Police Station Address	(Fax) +65-62446558
	20 Chai Chee Drive Singapore 469045
Was notice of intended Prosecution given?	No
If yes, against whom?	-
CIRCUMSTANCES OF ACCIDENT	
AS DED DOLLOS DEDODE NA T/20220707/21/2	
AS PER POLICE REPORT No,T/20220707/2142	
ATTACHMENT(S)	

Yes Yes

Are accident photos available for attachment? Was there any video captured by Car Camera?

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

-
-
-
-
Commercial vehicle
-
(Phone) +65-96952471
-
-
-
-
-
-
1

# **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number Vehicle Manufacturer	XD8827Z Scania
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	_
Address	-
Address complement	_
Postcode	_
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-

# **INJURED PERSONS DETAILS**

#### INJURED 1

Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	BAN YONG HOE Male (Phone) +65-81689448 10 PASIR RIS LINK #07-40 - 518163 47 CHEST PAIN XD7917D Yes No
INJURED 2	
Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	- - - - - - XD8827Z Yes


#### SKETCH PLAN

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act(PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My Insurer, my w orkshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) w ho have insured vehicle(s) involved in this accident (all insurer(s) w ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of;
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing w ith my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



## Describe Circumstances of the Accident

PLEASE REFER TO POLICE REPORT T /20220707/7038 AND T/20220707/2142

# Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time & 7/21

FLASH ACCIDENT COME PROPERTING OFFICER STATES OF THE PROPERTY OF THE PROPERTY

Witnessed by Reporting Centre Personnel







































Police Station Of Origin: Bedok N.P.C

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999

1 of 3 Report No. T/20220707/2142

REPORT	F A TRAFFIC	ACCIDENT			
Date/Time Report Made: 07/07/2022 22:32			Vide Report No.: T/20220707/7038	Station Diary No.: 99	
Informa	nt's Partice	ulars			
	f Informant: NG HOE		Address: BLK 10 PASIR RIS LINK #07	-40 SINGAPORE 518163	
	/ ID No.: O / S75680:	25B	Contact No.: Home/Office:	Mobile: 81689448	
National MALAY:	50 m. 100.00		Email:	10 10 10 10 10 10 10 10 10 10 10 10 10 1	
Sex: Male	Age:	Date of Birth: 09/03/1975	Type of Informant: Rider		
Race: Chinese			Language: Chinese	Institution / School Name:	
Occupation: Lorry driver			Driving Licence Information: Class: 2B,3,4,5	Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/07/2022 09:15	Type of Location: Straight Road	
Location:  AYER RAJAN  Weather: Clear	1 EXPRESSWAY	Road Surface:		Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collis	sion:			Anyone conveyed by ambulance:	

Vehide No.	Туре	Make	Model	Color	Condition	No of Passenge
XD7917D	Lorry			White	Seriously Damaged	
XD8827Z	Lorry			Orange	Seriously Damaged	(28%)
YL5831B	Lorry			White	Seriously Damaged	

Details of Person Involved	(Olou )
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Details of Vehicle Insurance

T/20220707/7036

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 2 of 4 Report No. T/20220707/7038

# CONTINUATION OF REPORT

Vehicle No.	Ins	urance Company	Insura	ance No	4.1	Effective		
XD7917D	ER		D22NB0000091			01/03/2022	28/02/2023	
Details of Po	erso	n Involved		14.	3.5.4	1.55		
Any Pedestri								
		s Injured: NIL	Use of F	edestrian	Cross	sing: NA		
Driver					4.1		27-770	
Name		BAN YONG HOE		ID No.		S7568025B		
Related Veh	icle	XD7917D (Lorry)		Conta	ct No.	81689448		
Hospital/Clin	ic	RAFFLESMEDICAL			of g e &	Class: 28,3,4,5 Date of Expiry: NIL		
Date		07/07/2022		07/07/2022				
No. of Days	grant	ed Medical Leave 05	of	f Slight				
Passenger	_					F 1 125 1		
Name		Unknown Passenger	ID No.		NIL			
Related Vehi	cle	XD7917D (Lorry)	Conta	ct No.	NIL	W		
Hospital/Clin	ic	NIL	Driving	Class of Driving Licence & Expiry		iry: NIL		
Date		NIL	Date		NIL			
No. of Days	grant	ed Medical Leave NIL	Degree	of				
Driver						1.54.45		
Name		MUHAMMAD IFDHAL BIN MAN	ID No.	ID No. S9416321H				
Related Vehi	cle	NIL	Conta	ct No.	NIL			
Hospital/Clini	ic	NIL			of 9 e &	Class: NIL Date of Exp	iry: NIL	
Date		NIL	Date		NIL			
No of Dave o	rant	ed Medical Leave NIL	Degree	of	NIL			



T/20220707/7038

Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 4 Report No. T/20220707/7038

#### CONTINUATION OF REPORT

Driver	Children Control		1 1 1 1 1 1 1 1		- 11	
Name	CHUA KEE HOO			ID No		S1180800Z
Related Vehicle	NIL			Conta	ct No.	96952471
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date	NIL Da		Date	•	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	f	NIL	

#### **Brief Details**

On 07 July 2022 at 0915am, I was driving my white Hino Lorry (XD7917D) along AYE towards TUAS on the third lane. While driving, I heard multiple loud collisions coming from the front of the bus in front of me. The bus in front of me came to an abrupt stop. As such, I engaged my brakes and came to a stop preventing myself from colliding with the bus.

However, a white color Mitubishi lorry (YL5831B) collided with the rear of my lorry. The seatbelt managed to prevent me from flying forward. I then alighted, took photos of the accident and exchanged particulars. I was then interviewed by Traffic Police officer and was advised to lodge an accident report.

Subsequently, I went over Raffles Medical located at Harbourfront Centre and received five days of MC due pain on my chest due to the seatbelt.

I wished to state that the rear steps of my lorry and right rear signal light were dislodged from my lorry. The rear siren was also dislodged. The rear bar meant for stepping was dented.





Police Station Of Origin: Bedok N.P.C 30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999

Report No. T/20220707/2142

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: G / SI CHOO CHUN NAM	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 07/07/2022 22:32
Officer In Charge Of Case: TP / AEIT / SR STAFF SGT FAHKRUL RAZI BIN SUHAIME Contact No.: 65470000	Classification Of Case:
NP158	

Gar

