

ASS. REC. BY: Taught

REF:

CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ms Luke

Veh No:

SHA 4543Z

Yr Regn: 2019, Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

C.C. 1580

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

330518

T/Radio: Insured / Std / NI / NA

Eng/No:

KMH C851C V L 4186599

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wet Hubs

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27/6/22

Survey held at

Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Invs

(\$

☐

Weekend

(\$

Report Format: _____

Lump Sum / L.B. / C: _____

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA4543Z

Make : HYUNDAI

Model : IONIQ(G3)

Date: 29.06.2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	EMBLEM – BLUE DRIVE RH			\$ 26.60
1	FRT FENDER RH			\$ 588.80
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH			\$ 28.00
1	FRT WHEEL HUB CAP RH			\$ 346.40
	SUB TOTAL			\$ 1,492.90
	LESS 20%			\$ 298.58
	DISCOUNTED TOTAL			\$ 1,194.32
	FRT DOOR COMFORTDELGRO LOGO RH			\$ 75.00
				\$ 75.00
	Labour Charge			
	PANEL BEATING			\$ 750.00
	SPRAY PAINTING CHARGE			\$ 800.00
	TUFF KOTE			\$ 60.00
	TOTAL LABOUR			\$ 1,610.00
	ESTIMATE TOTAL			\$ 2,879.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphu 97495749
 WP 21/6/22 @ 330pm
 c/s Resurvey after repair
 tanphu@hhaunt.com
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 29.06.2022 14:12

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4336517

JC NO305521488


CUSTOMER		REGN NO:	MILEAGE
COMFORT TRANSPORTATION PTE LTD		SHA4543Z	
IR/MS	7010045	MAKE:	FUEL
CUSTOMER NO		HYUNDAI	E.....1/2.....F
ADDRESS	383 SIN MING DRIVE	MODEL	DATE/TIME IN
	Singapore SINGAPORE 575717	IONIQ(G3)	29.06.2022 10:20
EL. (R)	65508755	YR OF MANU.	TARGET DATE
(P)		20.10.2019	
DISCOUNT CARD NO.		CHASSIS CODE	COMPLETION DATE/TIME:
		KMHC851CVLU186599	

JOB DESCRIPTION

Accident Date: 28.06.2022

NATURE: 3P 28.06.2022'

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

re:
Vo.:
icle No.: **SHA4543Z** **YY**

Vehicle No.: **SHA4543Z**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

ie returned to Service Reception upon collection

To be kept by Security Guard