

Our Job Ref No : 305521488 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 Date 01/07/22 **FINALIZATION FORM** LKK Fax: Taufikh Attn : Mr\_\_\_\_ Vehicle Reg No. : SHA4543Z 28.06.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-1. The repair job shall bill to: **CHINA TAIPING** SMX2403C The finalized amount shall be: 2. Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost \$0.00 Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% Final Lumpsum Repair cost \$1,350.00 3. Estimated normal period for repairs: 2 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 4. 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Taufikh Name : Ms. Loke YY Name 31/8/22 Tel 62148355 Date Fax 65468156 For Official Use Only Document Confirm By Item Amount Attached Remarks (Signature) Yes or No Rental Rate P/Day YES 2. Loss of Income Paid NO Survey Fees 4. LTA Search Fee \$7.49 / \$2.00 5. Medical Fees (on behalf of driver, if applicable)

6 Overrun

Remarks: