

ASS. REC. BY:

REF: SMO/ 220066001ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s SG 98

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: JPE 9263 Yr Regn: 03, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 135CC c.c. 135Colour Orange / Black A/C: Insured / Std / NI / NASp. Reading 11339 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMYKG 05400 . 0095524Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Diamond 701POR17
R: Retzeler 801POR17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 3 mm

Rear

R/Bal. 5 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 30/6/22D.O.I. 13/7/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S & o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2019	11:00	84001	Cat 1 & 04 days (Red \$3,559.50 / 90%)
------	-------	-------	--

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S - RS. SI

) Exp. is

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

JPE 9263



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

BNWFUE0D

No. Pendaftaran	: JPE9263
No. ID	: 860620335515
Nama Pemunya Berdaftar	: HOI KAH YANG
Alamat	: H-232 KAMPUNG KEMANSUR 28700 BENTONG PAHANG
No. Chasis/No. Enjin	: PMYKG0540D0095524 / G399EE095524
Buatan>Nama Model	: YAMAHA / YAMAHA 135LC
Keupayaan Enjin	: 135
Bahan Bakar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: MOTOSIKAL
Jenis Badan/Tahun Dibuat	: MOTOSIKAL / 2013
Tarikh Pendaftaran	: 08/03/2013
B. D. M/B. G. K/BTN	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -

CERTIFICATE OF INSURANCE

Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia)
Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
Motor Vehicles (Third Party Risks & Compensation) Rules 1960 (Republic of Singapore)
Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam

MOTOR - MOTOR CYCLE PRIVATE	Comprehensive	RM	1,500.00
	Excess All Claims	RM	100.00
MY3 – Motor Cycle Private			
Index Mark and Vehicle Registration No.		Policy No.	
JPE9263		CVC-V6730168-J1	
Name of Insured			
HOI KAH YANG			
Effective Date of the Commencement of Insurance for the purpose of the Regulations, Ordinance or Enactment		Date of Expiry of Insurance	
22/05/2022		21/05/2023	
Persons or Classes of Persons entitled to drive Any person who is driving on the Policyholder's order or with their permission Limitations as to use Use only for social, domestic and pleasure purposes and in connection with the Policyholder's business or profession. The Policyholder does not cover: a) Use for hire and reward b) Use for racing, pace-making, reliability trial or speed-testing c) Use for the carriage of goods (other than samples) in connection with any trade or business d) Use for any purpose in connection with the Motor Trade Limitation rendered inoperative by Section 93 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not included under this heading. I - We certify that the Policy to which this Certificate relates is issued in accordance with the provision of Part IV of the Road Transport Act, 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.			
For and behalf of Etiqa General Insurance Berhad			

JPE9263 - Cert 2022 - 2023.pdf

THE SCHEDULE



STAMP DUTY PAID

Policyholder HOI KAH YANG H-232 KAMPUNG KEMANSUR 28700 BENTONG BENTONG 28700 PAHANG	Policy No : CVC-V6730168-J1 Account No. : V0032018 Agent Name : KKK NETWORK & ENGINEERING Product Type : Motor Cycle Private Period of Insurance from 22/05/2022 To 21/05/2023 (both Dates inclusive). Any subsequent period for which the Insured shall pay and the Company shall agree to accept a renewal premium.
--	---

NRIC No : 860620-33-5515 Business/Occupation : Administrator Vehicle Information JPJ Document No Vehicle Reg No : JPE9263 Make : YAMAHA Model : YAMAHA 135LC NA Engine No : G399EE095524 Chassis No : PMYKG0540D0095524 Year of Manufacture : 2013 Cubic Capacity : 135 Seating Capacity : 2 Financial Interest : NIL Business Reg No : Other ID No : Log Book No : NIL Cover Type : Comprehensive Vehicle Type : Motor Cycle Private License Type : Normal Cycle Use For : Private Use Rider Type : All Riders	Sum Insured : RM 1500.00 Gross Premium : RM 218.15 Less: No Claim Discount 0.00% : RM 0.00 Add: Service Tax 6.00 % : RM 13.09 Stamp Duty : RM 10.00 TOTAL AMOUNT DUE : RM 241.24 Excess Damage Claims : RM 100.00
--	--

MEMO

INFORMATION ON ePOLICY

In line with our Group's strategy to promote usage of technology and to help preserve the country's natural resources, we no longer print the full policy wording. You may view and print the above policy wording at our website www.etiqa.com.my. Printout may also be obtained from our offices nationwide.

SANCTION LIMITATION AND EXCLUSION CLAUSE

This insurance policy shall not provide cover and the Company shall not be liable to pay any claim or provide any benefit hereunder to the extent that the provision of such cover, payment of such claim, or provision of such benefit would expose the Company to any Sanction, prohibition or restriction under the CISAD Act or United Nations resolutions or trade or economic sanctions, laws or regulations of the European Union, United Kingdom.

Wef 1 Jan 2014, prohibition or restriction under the CISAD Act is replaced by laws or regulations of United States of America

MINIMUM PREMIUM

The Policy is subject to RM20.00 minimum premium

Issue Date : 22-05-2022/01:46 PM

Issue At : J1

Issue By : v0032018

For and on behalf of
 Etiqa General Insurance
 Berhad



Visit www.etiqa.com.my or our nearest branch to obtain the full policy wordings.
 Help preserve the country's natural resources.

Visit www.etiqa.com.my or our nearest branch to obtain the full policy wordings.
 Help preserve the country's natural resources.





**SINGAPORE
POLICE FORCE**



T/20220630/2049

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

2 of 4

Report No. T/20220630/2049


CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
JPE9263	ETIQA INSURANCE BERHAD	CVC-V6730168-JI	22/05/2022	21/05/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	HOI KAH YANG	ID No.	G8306207Q
Related Vehicle	JPE9263 (Motorcycle)	Contact No.	83567868
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/06/2022	Date Discharge	30/06/2022
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	UNKNOWN	ID No.	NIL
Related Vehicle	SLB7864A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	UNKNOWN	ID No.	NIL
Related Vehicle	SMQ7705K (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



**SINGAPORE
POLICE FORCE**



T/20220630/2049

1 of 4

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Report No. T/20220630/2049

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 30/06/2022 14:41		Vide Report No.:		Station Diary No.: 103	
Informant's Particulars					
Name of Informant: HOI KAH YANG		Address: 255 ALEXANDRA ROAD SINGAPORE 159937			
ID Type / ID No.: FIN NO / G8306207Q		Contact No.: Home/Office:		Mobile: 83567868	
Nationality: MALAYSIAN		Email: kahyang6587@gmail.com			
Sex: Male	Age: 36	Date of Birth: 20/06/1986	Type of Informant: Rider		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Automotive engineering technician		Driving Licence Information: Class:		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/06/2022 08:00	Type of Location: Straight Road
Location: BUKIT TIMAH ROAD				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	Notes
JPE9263	Motorcycle	YAMAHA	135 LC	Red	Seriously Damaged	0
SLB7864A	Car	HONDA	SHUTTLE 1.5G CVT	Silver	Slightly Damaged	0
SMQ7705K	Car	BMW	216i ACTIVE TOURER	Black	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20220630/2049

3 of 4

Report No. T/20220630/2049

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

CONTINUATION OF REPORT

Brief Details.

I am the vehicle owner of JPE 9263 (Yamaha LC 135, Red). Currently I am working as a Technician under Kah Motor Company Sdn. Berhad located at 255 Alexandra Road Singapore 159937.

On 30/06/2022 at about 08000 hrs, I was travelling along BKE towards SLE for work. I was travelling on the middle between right 1st and 2nd lane. While travelling, a car on the 2nd suddenly signal right and did not check on coming vehicle and just wanted to cut into Lane 1. As the car suddenly wanted to filter right onto 1st lane, I was unable to stop in time and hit onto the car front side mirror and right body of car which causes dent on the car. My motorcycle subsequently hit another car on the right 1st lane. Due to that, I fell onto the ground with my motorcycle.

I wish to inform that after I fell onto the ground, another motorcycle hit onto my motorcycle and the rider was flung off and landed on top of me. Afterwhich, we help each other up and subsequently waited for Traffic Police and Ambulance to come.

The Ambulance came and the paramedics subsequently conveyed me to National University Hospital. I wish to inform that I was given 5 days outpatient sick leave starting from 30/06/2022 to 04/07/2022.

I do not have the motorcycle registration number and only have the other two car which involved in the accident. The other 2 cars registration number are as follows:

- 1) SLB 7864A
- 2) SMQ 7705K

On 30/06/2022 at about 1124 hrs, I received a message from Traffic Police, Investigation Officer, Ms Hafizah and she has advised me to lodge a Traffic Accident report.



**SINGAPORE
POLICE FORCE**



T/20220630/2049

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

4 of 4

Report No. T/20220630/2049

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:
D /
SI WONG CHONG WAI

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Other MUHAMMAD SYARIFUDDIN
MUHAMMAD AJMAIN
Contact No.: 65476367

Signature Of Informant:

Date/Time:
30/06/2022 14:41

Classification Of Case:

NP168

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12/7/2022

To : LKK

Attn :

Tel :

*Not Withheld
11 Days @ 400h
Recovery After Paving
4 days*

By Fax:

VEHICLE NO : JPE 9263

Yamaha 135 LC

ACCIDENT DATE: 30/6/2022

Description	Qty	Quotation \$
1 Handle Bar <i>Sn</i>	1	95.00 X
2 Brake Lever <i>Pex</i>	1	75.00 X
3 Mirror <i>nd</i>	1 Set	120.00 ✓
4 Headlamp <i>Gr</i>	1	280.00 ✓
5 Headlamp Cover <i>nd/cm</i>	1	150.00 ✓
6 Head Cover Panel <i>?</i>	1 <i>Sn</i>	120.00 X
7 Inner Panel <i>cm</i>	1	115.00
8 Signal RH <i>?</i>	1 <i>Sn</i>	75.00 X
9 Fork Tube <i>?</i>	1 <i>Sn</i>	480.00 X
10 Fork Oil Seal <i>?</i>	1 <i>Sn</i>	125.00 X
11 Fork Under Bracket <i>?</i>	1 <i>Sn</i>	210.00 X
12 Front Mudguard <i>cm</i>	1	135.00 ✓
13 Front Rim <i>1 RX</i>	1	250.00 X
14 Front Side Fairing L/RH <i>Br/cm</i>	1	250.00 ✓
15 Radiator <i>nd/Pn</i>	1	280.00 ✓
16 Radiator Cap <i>1 SnX</i>	1	120.00 X
17 Centre Leg Shield <i>MIT</i>	1	110.00 ✓
18 Engine Lower Cover <i>cm</i>	1	135.00 ✓
19 Rear RH Panel <i>SnX</i>	1	125.00 X
20 Foot Rest <i>At</i>	1	90.00 ✓
21 Foot Rest Rubber <i>cm</i>	1 Set	55.00 ✓
22 Pillion Bar <i>RX</i>	1	90.00 X
23 Box Rack <i>nd/RX</i>	1	110.00 X
24 Radiator Fan Motor <i>SnX</i>	1	260.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total

Less 10%

Sub-Total

0.00

0.00

0.00

\$3,855.00

\$ 385.50

\$3,469.50

Total

VEHICLE NO : ~~JSQ 2784~~
JPE 9263

Yamaha 135 LC

Nett items

1	Towing fees	40.00	301
2		250.00	1001
	Remove & replace parts, align & etc		
3	Remove & replace Fork Tube & Top Up Fork Oil	120.00	801
4	Supply Body Decal Sticker	80.00	601
5	IU Unit <i>SW X</i>		
6	Rear Box <i>104/61</i>		
7	Number Plate (Sticker) <i>MC</i> <i>PM</i> 1 Set		

Sub-Total 490.00

Nett Total 490.00

Grand Total \$ 3,959.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts (if any) resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary items must be approved and
is subject to final approval from Insurance Company
Acknowledged by repairer:
Signature:
Date: