

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 12/7/2022

To : LKK

Attn :

Tel :

Not Notified
11 Days @
Repairing After Repair

By Fax:

VEHICLE NO : JPE 9263

Yamaha 135 LC

ACCIDENT DATE: 30/6/2022

	Description	Qty	Quotation \$
1	Handle Bar ?	1	
2	Brake Lever <i>Plex</i>	1	
3	Mirror <i>Red</i>	1 Set	
4	Headlamp <i>Gr</i>	1	
5	Headlamp Cover <i>Red/CM</i>	1	
6	Head Cover Panel ?	1	
7	Inner Panel <i>CM</i>	1	
8	Signal RH ?	1	
9	Fork Tube ?	1	
10	Fork Oil Seal ?	1	
11	Fork Under Bracket ?	1	
12	Front Mudguard <i>CM</i>	1	
13	Front Rim ?	1	
14	Front Side Fairing L/RH <i>Red/CM</i>	1	
15	Radiator <i>Red/Pu</i>	1	
16	Radiator Cap ?	1	
17	Centre Leg Shield <i>MIT</i>	1	
18	Engine Lower Cover <i>CM</i>	1	
19	Rear RH Panel ?	1	
20	Foot Rest <i>RI</i>	1	
21	Foot Rest Rubber <i>CM</i>	1 Set	
22	Pillion Bar ?	1	
23	Box Rack <i>Red/CM</i>	1	
24	Radiator Fan Motor ?	1	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub-Total 0.00
Less 10% 0.00
Sub-Total 0.00

From
Estimate
OD
To
at

**SINGAPORE
POLICE FORCE**



T/20220630/2049

3 of 4

Report No. T/20220630/2049

CONTINUATION OF REPORT

Brief Details.

I am the vehicle owner of JPE 9263 (Yamaha LC 135, Red). Currently I am working as a Technician under Kah Motor Company Sdn. Berhad located at 255 Alexandra Road Singapore 159937.

On 30/06/2022 at about 08000 hrs, I was travelling along BKE towards SLE for work. I was travelling on the middle between right 1st and 2nd lane. While travelling, a car on the 2nd suddenly signal right and did not check on coming vehicle and just wanted to cut into Lane 1. As the car suddenly wanted to filter right onto 1st lane, I was unable to stop in time and hit onto the car front side mirror and right body of car which causes dent on the car. My motorcycle subsequently hit another car on the right 1st lane. Due to that, I fell onto the ground with my motorcycle.

I wish to inform that after I fell onto the ground, another motorcycle hit onto my motorcycle and the rider was flung off and landed on top of me. Afterwhich, we help each other up and subsequently waited for Traffic Police and Ambulance to come.

The Ambulance came and the paramedics subsequently conveyed me to National University Hospital. I wish to inform that I was given 5 days outpatient sick leave starting from 30/06/2022 to 04/07/2022.

I do not have the motorcycle registration number and only have the other two car which involved in the accident. The other 2 cars registration number are as follows:

- 1) SLB 7864A
- 2) SMQ 7705K

On 30/06/2022 at about 1124 hrs, I received a message from Traffic Police, Investigation Officer, Ms Hafizah and she has advised me to lodge a Traffic Accident report.



**SINGAPORE
POLICE FORCE**



T 20220630/2049

2 of 4


Report No. T:20220630/2049

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129658
Tel No: 1800-8729999

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
JPE9263	ETIQA INSURANCE BERHAD	CVC-V6730168-JI	22/05/2022	21/05/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	HOI KAH YANG	ID No.	G8306207Q
Related Vehicle	JPE9263 (Motorcycle)	Contact No.	83567868
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/06/2022	Date Discharge	30/06/2022
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Driver			
Name	UNKNOWN	ID No.	NIL
Related Vehicle	SLB7864A (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	UNKNOWN	ID No.	NIL
Related Vehicle	SMQ7705K (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

BNWFUEOD

No. Pendaftaran	: JPE9263
No. ID	: 860620335515
Nama Pemunya Berdaftar	: HOI KAH YANG
Alamat	: H-232 KAMPUNG KEMANSUR 28700 BENTONG PAHANG
No. Chasis/No. Enjin	: PMYK00540D0095524 / 8399EE095524
Buatan>Nama Model	: YAMAHA / YAMAHA 135LC
Keupayaan Enjin	: 135
Bahan Bakar	: PETROL
Status Asal	: PEMASANGAN TEMPATAN
Kelas Kegunaan	: MOTOSIKAL
Jenis Badan/Tahun Dibuat	: MOTOSIKAL / 2013
Tarikh Pendaftaran	: 08/03/2013
B.D. M/B. G. K/BTH	: -
Syarat Pendaftaran 1	: -
Syarat Pendaftaran 2	: -
Syarat Pendaftaran 3	: -