

REFERENCES

From: _____ Date: _____

Veh No: 7Q3787 H. Yr Regn: 2021 / June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino XZ4710R C.C. 4009

Colour White A/C: Insured / Std / NI / NA

Sp. Reading 17764 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: THH4CV3F20K038546

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

N/S	O/S

R: 195/85 R16.

R: 195/85 R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO OT

Front

R/Bal. ϕ_b mm R/Bal. ϕ_b mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 13/07/22

Vehicle: IN / OUT

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Action / Instruction

TP A16.

MV :

PV:

Nett:

338 N

☐ : Prel. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Report Form 8

☐ Interview (\$

Tech. Invs (3)

Survey Fee:

Transportation:

$$S \div RS. \quad S$$

Photos

1	Others	1
---	--------	---