

Service Request Details

Claim	S2M0466T
Reference	CS3/ASM22006617/Gvy3m4 
Loss Date	6 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	11 Jul 2022 3:22:00 PM
Request Date	13 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	GBB6418E
Vehicle	
Registration #	
Make	TPVD Toyota
Model	Dyna

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOH Cynthia

cynthia.loh@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2204362.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 July 2022
 GBB 6418E IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 July 2022
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	12 July 2022
 TP GIA (GBB6418E).pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	12 July 2022
 Insd GIA (SH8715B).pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	8 July 2022