

CC6/A1622006628/4p93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JSX2946

at Workshop m/s Enfe

of analysis

Insured: SKE 9226A

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: JSX2946 Yr Regn: 31/07/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha 135LC c.c. 134

Colour multi colour A/C: Insured / Std / NI / NA

Sp.Reading 89/45 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PMYUG0810J0038196

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or affected

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/P / STD A/P or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: RM 5k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT _____

Veh No: JSX2946 Yr Regn: 31/07/18
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha 135LC c.c. 134
Colour: multi colour A/C: Insured / Std / Nil / NA
Sp. Reading: 89/45 T/Radio: Insured / Std / Nil / NA
Eng/No:
C/No: PMYUG0810J0038196
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or affected
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 70-90-17
R: 70-90-17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or maxxis
Front 6 Rear 6
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. 29/06/22 D.O.I. 13/7/22
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
MS front & O/S body
The U/C / Chassis frame / Body Structure affected due to collision.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

\$1600?

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)
Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

□: Interview (\$

□: Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

$$) \text{---} S + RS, \text{---} SI$$

) Photos

) Others

TOTAL



Yamaha 135LC 2018 tahun
RM 6 500

Used
2018



Today, 07:35



Kuala Lumpur



second lc Lc135 LC lc135 yamaha used ready murah
RM 4 500

Used
2018



Yesterday,
11:15



Johor



second lc Lc135 LC lc135 yamaha used ready murah
RM 4 500

Used
2018



Yesterday,
11:15



Johor



second lc Lc135 LC lc135 yamaha used ready murah
RM 4 500

Used
2018



Yesterday,
11:10



Johor



second lc Lc135 LC lc135 yamaha used ready murah
RM 4 500

Used
2018



Yesterday,
11:10



Johor



Yamaha lc135 135lc lc 135 jsp4066 v6 2018
RM 6 500

Used
2018



Yesterday,
10:02



Johor



lc135 Lc135 Yamaha LC Lc lc used Used second murah
RM 4 500

Used
2018



Yesterday,
08:02



Johor



Yamaha LC v5
RM 5 400

Used
2018



Jul 10, 10:42



Selangor



Yamaha 135LC
RM 5 800

Used
2018



Jul 9, 16:28



Kedah



yamaha lc135 4s v4
RM 6 200

Used
2018



Jul 8, 15:23



Penang



Lc135 v4 Tahun 2018 spec
RM 5 700

Used
2018



Jul 8, 14:56



Kuala Lumpur