



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD  
BLK 1 KAKI BUKIT AVE 6  
#01-28/53/55/56 (MAIN OFFICE) SINGAPORE  
417883  
ON BEHALF OF YEH HEN SOON

Ref: CS/TP22006644/Uqy3e2  
Date: 29/08/2022  
Code: TP149

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLA 5986A
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	14/07/2022

### 2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 EX (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KNAFX411MG5596206	Colour	GREY
Odometer	131893 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	GOODYEAR	7 mm
L/H Front Tyre	225/45 R17	GOODYEAR	7 mm
R/H Rear Tyre	225/45 R17	GOODYEAR	7 mm
L/H Rear Tyre	225/45 R17	GOODYEAR	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	09/07/2022	Inspection Date	14/07/2022
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 25 Working Days