

(08/11/0) wef
ASS. REC. BY: RAM

REF: CS3/CT122006646/Rug3

6946

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKN 8479X

at Workshop m/s King's auto

of 176 PIN MINH DR #02-10

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 37K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKN 8479X Yr Regn: 2014 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLKSWAGEN GOLF A714TDC 1395

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 115292 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZW428415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 06/07/22

Survey held at

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

REPAIR LIMIT - 19K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 3 days

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	694G
Vehicle No.:	SKN8479X
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT 5G13GZ SR MID
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	CXS209778
Chassis No.:	WVWZZZAUZEW428915
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$22,711.00
Original Registration Date:	23 Jul 2014
First Registration Date:	23 Jul 2014
Transfer Count: -	0
Actual ARF Paid:	\$8,796.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2024
PARF Rebate Amount:	\$5,277.00
COE Expiry Date:	22 Jul 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,899.00
COE Rebate Amount:	\$12,429.00
Total Rebate Amount:	\$17,706.00

The information contained herein is correct as at 19 Jul 2022

OK

Volkswagen Golf 1.4A TSI Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



GLAMOUR
AUTOMOTIVE
PTE LTD

Accreditation



Member of:



Price	\$37,800		
Depreciation ⓘ	\$16,590 /yr View models with similar depre	Reg Date	24-Jul-2014 (2yrs 4days COE left)
Mileage	N.A.	Manufactured ⓘ	2014
Road Tax ⓘ	\$624 /yr	Transmission	Auto
Dereg Value ⓘ	\$16,634 as of today (change)	OMV ⓘ	\$22,711
COE ⓘ	\$56,396	ARF ⓘ	\$8,796
Engine Cap	1,395 cc	Power	90.0 kW (120 bhp)
Curb Weight ⓘ	1,249 kg	No. of Owners ⓘ	4