

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 22.06.2022
Time: 15:06:15
Page: 1

Ohnir (Wum)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305520712
REGN NO : SH 7079K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.04.2016
DATE/TIME IN : 22.06.2022 13:00
ACCIDENT DATE : 21.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	de	
0002	04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	RP	
0003	04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	RP	un
0004	04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	RP	un
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	net	✓ 575
0006	04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	net	✓ 20% 460 SN50

JOB NATURE

0000	PB	PANEL BEATING	300.00	280		460
0001	SP	SPRAYPAINT CHARGE	300.00	250	560	50 250 560
0002	L	REMOVE/REFIX REVERSE SENSOR	50.00	30		1820

SUB-TOTAL : 650.00 4/5/1050

Tanah 97495749
wp. 22/6/22 @ 4pm
4/5 days after repair
2 days
further @ 11h am 10m

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 days