

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Reg. No: 19960	/198R GST Reg. No. 19	-96071	198-R	
		Affiliated to Federation Internatio	nale Des Experts En Au	utomol	bile	
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22006667/Ucy3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	27/07/2022	
			Co	ode:	AGI	
1.		Policy Particulars	:- THIRD PARTY C	LAIM		
	Insured Veh.	SJZ 4230X	Veh. Inspected		SMN 6893Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10014933/CD	Excess (\$)		0.00	
	Assign From	SHAFAWATI MD RABU	Assign Date		14/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI AVANTE (A)	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KMHD841CMKU917416	Colour		GREY	
	Odometer	148788 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MAXIMUM		6 mm	
	L/H Front Tyre	195/65 R15	MAXIMUM		6 mm	
	R/H Rear Tyre	195/65 R15	MAXIMUM		6 mm	
	L/H Rear Tyre	195/65 R15	MAXIMUM		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	24/04/2022	Inspection Date		12/07/2022	
	Survey held at	FOCUS AUTO PTE LTD				
		NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883				
5a.	. Remarks					
	A)THE INSPECTION	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D)IN ACCORDANC	Estimate Days of Repair				
	Louinate Days of Nepan					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: