

Service Request Details

Claim	S2M046MP
Reference	CS/ASM22006678/Uvy3m4 
Loss Date	10 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	14 Jul 2022 9:48:56 AM
Request Date	14 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information	
Incident	PC3699J
Vehicle	
Registration #	
Make	TPVD TOYOTA
Model	HIACE
Service Address	
, , ,	
Primary Contact/Insured	

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty

kitty.teo@axa.com.sg

Additional Instructions

- Messages1
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2204713.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	29 July 2022
 PC3699J TP GIA.pdf.pdf	Reports & Statement	GIA Report	TEO Kitty	29 July 2022
 PC 3699J IA.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 REPLY FORM SOLICITOR.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	14 July 2022
 SHA6951R OI GIA.pdf.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 July 2022
 EMAIL FORM SOLICITOR FOR TP REG.msg.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	14 July 2022