

Service Request Details

Claim	S2M046M5
Reference	CS/ASM22006680/Kqy3m4 
Loss Date	13 July 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	14 Jul 2022 9:16:21 AM
Request Date	14 July 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information	
Incident	SLP1185S
Vehicle	
Registration #	
Make	TPVD
Model	HONDA
Service Address	
, , ,	
Primary Contact/Insured	

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2205357.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	31 August 2022
 SLP 1185S-IA.pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 August 2022
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	14 July 2022
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	14 July 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SHD5700P INS GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	14 July 2022
 SLP1185S TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	14 July 2022
 PRS TP.pdf.pdf	Legal	Others	KUMAR Shailendra	14 July 2022