ASS. REC. BY: Marcus REF: CS3/SM022003033/4943	
	<u>ASSIGNMENT</u>
From: Date:	Veh No: 5/47 78 Str 3 Yr Regn: 23/06/15
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TPTWS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: VOLVO 5 (20 c.c 1(70)
at Workshop m/s EVEF GUM	Colour Consul A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured: GBB4932A	Eng/No: 7750/
Policy No.	C/No: YVIFS84ABF 2365887
Claims No. CMTD 2201084 /MYE	Gen. Copd: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R: 215-/55-2/1
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA (NC) OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 6 4V 4	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 7 mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 7 mm L/Bal. 7 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 30/3/22 D.O.I. 1/4/22
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 907J	
Vehicle: IN / Date: Person Contacted: L7A 5	OUT
779097(The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time Action/Instruction Dep Me.	
1/4/22 Survey of @11.200	v.
715mill on 1/4/22 @	1.45pm.
1/4/22 Survey of C/11.20an Disneth on 1/4/22 @ Albir 18jeir OM 7/4/22@ 1/22 Suburt Rejai roye &	5.38pm.
AUC Suburt Reja roye	1400 - 5800
14/22 Submit PRS.	
07/22 Submit LS \$4400, 4 days (Red \$520	00. 54%)
Date/Time, File Pass to? : Preli. Report	
1) 12/4 turist : Final Report	
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
	Fee: : Site Insp (\$) _s+Rs,_si
-,	: Interview (\$) Photos
Report Format: PRS	: Tech. Invs (\$) Others
,	
Lump Sum / I.B.I: (\$: Weekend (\$