St. RECORDY: Steve " (S/AIS 2200	
	VEN NO: SMF 9862J YEREGIN: 30/11/18
From: Date:	Veh No: Yr Regn: Solling Mover!
Eslimated Cost:	Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
ODY TP I WS I TP RES I OD RES I EVA I INV I MY	Truck/Traller or Subaru Forester c.c. 1995
To Inspect Vehicle No:	Make: A/C: Insured / Std / NI / NA
at Workshop m/s	USTOVVII TRadio Insured Std / NI / NA
of	Sp.Reading USO77
Insured:	Eng/No: JF18J5KCSJG117420
Policy No.	CNO: JP/SJSA COUTTY of PERSON A COUNTY OF PERSON A
Claims No.	Gen. Cond; Good / Fair / Poor / Burnt Steering: Inorde) / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
(Cliont's Record)	
Make of Veh:	(1, 1, 1)(1)(1)
NOR OF THE	Tyre Size: F: // C/T Tyre Size: F: // R: // PIR/SUM/
(Defley Condition)	R:
(Policy Condition) Remark: The veh had commenced its N/S 0/S	TOYOTYOKO OF LAUYEN
repair at the time of inspection.	TOYO / YORO 67
Bal. or Market Value:	Fron! R/Bal. W mm
IDAC Accident Rport: Consistent? : Yes or No	UBal. 4 mm
Cancistent? · Yes or No	DOI: 15/1/1/
days Res.: Yes or No	Chy taff
est Repairs 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Lum Sum: 70	Des. of Damages : From RH
CA / REV / REP. / 24 HRS Vehicle: IN/C	The U/C / Chassis frame Body Structure affected due to collision.
Date:Person Contacted:	
Date / Time Action / Instruction	
MY- 43A	
·	
1	
Dale/Time, File Pass to? : Prell. Report	Days Of Repair: Survey Fee:
Oste/Time, Fue Passer : Final Report	Resurvey No. of Trip: Survey Fee:
1	- 1 seps SI
Oatertune, rue Manager	Id Fee: Site Insp
. 2)	. Interview (
Report formet:	:Tech, invs (*
Lump Sun (I.C. f: (5)	:Weellend (\$
Fittib Garage	
to the state of th	·
· · · · · · · · · · · · · · · · · · ·	



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065 Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER:

Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Ref. No:

WSK/JW/SF-SMF9862J

SP2000035725-01

Date of Loss:

05/07/2022

Policy No:

Driveable?

Vehicle Reg. No.:

SMF9862J 64 / MALE

Party At Fault:

UNKNOWN

Driver Age/Info:

NO

Third Party Involved? YES

TP Injury Involved? Insured/Claimant:

WEE CHEE WAI WEE CHEE WAI Contact No:

+6596646608

Driver:

Make/Model:

SUBARU FORESTER, 2.0 I-L CVT

Vehicle Reg. Date:

30/11/2018

Vehicle Colour:

AWD SR (A) **BROWN**

Chassis No:

JF1SJ5KC5JG112420

Engine No:

Odometer:

FB20YE45561

43097 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

20

Remarks:

VEHICLE IS IN.

Present Location:

SHU FATT AUTO WORKS (HQ)

		Amount
COST OF CLAIMS		13,067.40
Parts		1,380.00
Miscellaneous Items		3,200.00
Labour		1,800.00
Paintwork Labour		0.00
Towing	Calculated Gross Total (S\$)	19,447.40
	- Excess (S\$)	600.00
	(\$\$)	18,847.40
	+ GST 7.00% (S\$)	1,319.32
	Nett Amount (S\$)	20,166.72

This claim is handled by: PATRICIA KOH

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LICIC to survey on 15/7/22 14/1/22

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 14 Jul 2022) Part Source: MRM-SG

SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0) M1-SUV Parts:

(Price-denominated Standard List) Repairer's Labour: Print Code: Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

	stimates on . Qty Part No.	Particulars	%Disc	%Depr	Amount
		. 1	0.00	0.00	*600.00 F
2	1	*Front bonnet X K *Front bonnet chrome / (MT	0.00	0.00	*100.00 F
3	8		0.00	0.00	*20.00 F
4	1	APPROXIMATION AND AND AND AND AND AND AND AND AND AN	0.00	0.00	*60.00 F
5	12	*Front bonnet insulator X *Front bonnet insulator clips X	0.00	0.00	*30.00 F
6	2	*Front bonnet hinges X	0.00	0.00	*60.00 F
7	1	*Front bonnet lock X	0.00	0.00	*75.00 F
3	1	*Left front headlight	0.00	0.00	*1,650.00 F
)	1	*Right front headlight / BR	0.00	0.00	*1,650.00 F
0	1	*Left front headlight holder	0.00	0.00	*35.00 F
1	1	*Right front headlight holder / M'	0.00	0.00	*35.00 F
2	1	*Front top grille / CR	0.00	0.00	*130.00 F
3	6	*Front top grille clips \(\square\ \eta(0.00	0.00	*15.00 F
4	1	*Front lower grille / CUT	0.00	0.00	*230.00 F
5	12	*Front grille clips / nc	0.00	0.00	*30.00 F
6	1	*Front grille emblem / M(0.00	0.00	*55.00 F
7	1	*Front bumper / PR	0.00	0.00	*340.00 F
8	1	*Front bumper reinforcement ~ 00	0.00	0.00	*220.00 F
9	1	*Left front bumper bracket / 🍂	0.00	0.00	*18.00 F
0	1	*Right front bumper bracket	0.00	0.00	*18.00 F
1	1	*Front bumper foam 1	0.00	0.00	*90.00 F
2	16	*Front bumper clips	0.00	0.00	*40.00 F
3	1	*Left front bumper retainers <	0.00	0.00	*12.00 F
4	1	*Right front bumper retainer / ///	0.00	0.00	*12.00 F
5	1	*Right front headlight washer nozzle / DR	0.00	0.00	*60.00 F
ŝ	1	*Right front headlight washer nozzle cover / M	0.00	0.00	*40.00 F
7	1	*Right front headlight washer pipes / 7h	0.00	0.00	*55.00 F
3	1	*Right front fog light / GR	0.00	0.00	*180.00 F
9	1	*Right front fog light chrome garnish / MIS	0.00	0.00	*40.00 F
)	1	*Right front fender / 000	0.00	0.00	*170.00 F
1	1	right fold folder cowing	0.00	0.00	*96.00 F
2	12	*Right front fender cowling clips / NC	0.00	0.00	*30.00 F
3	1	*Front air resonator / MIS	0.00	0.00	*40.00 F
	1	*Front lower engine cover / DR *Front lower engine cover clips	0.00	0.00	*120.00 F
,	12		0.00	0.00	*30.00 F
1	1	*Right air bag sensor ½	0.00	0.00	*135.00 F
	1	*Front support panel / 00	0.00	0.00	*280.00 F
3	1	*Front support lower member / 00)	0.00	0.00	*120.00 F
)	1	*Front mud flap / MIS	0.00	0.00	*180.00 F
•	1	*Front air intake hose 2 / (Ry	0.00	0.00	*281.00 F
	4	*Front air intake hose clips 7 ***	0.00	0.00	*14.00 F
	1	*Front top air box & / MR (AM)	0.00	0.00	*60.00 F
	1	*Front lower air box / OR (A)	0.00	0.00	*120.00 F
	1	*Front radiator	0.00	0.00	*900.00 F
5	1	*Front aircon condenser	0.00	0.00	*400.00 F

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section. Generated using Merimen e-Claims IEAS

/				%Disc	%Depr	Amount
No.	Qty	Part No.	Particulars			1210 00 E
			*Right front shock absorber / BT	0.00	0.00	*210.00 F
46	1		*Right front shock absorber top mounting - Pl	0.00	0.00	*95.00 F
47	1		*Right front shock absorber top bearing	0.00	0.00	*95.00 F
48	1		*Right front shock absorber bush / PC	0.00	0.00	*18.00 F
49	1		*Right front lower arm / 17	0.00	0.00	*310.00 F
50	1		Right Holit letter and	0.00	0.00	*160.00 F
51	1		Tright have	0.00	0.00	*35.00 F
52	1		Right Hone tower arm busin (1)	0.00	0.00	*45.00 F
53	1		Right from forter and the control of	0.00	0.00	*105.00 F
54	1		*Right front wheel hub / //K	0.00	0.00	*90.00 F
55	1		Right front wheel searing	0.00	0.00	*190.00 F
56	1		Tront and Ton 201	0.00	0.00	*20.00 F
57	2			0.00	0.00	*600.00 F
58	1		*Right front drive shaft	0.00	0.00	*45.00 F
59	1		*Right tie rod / 07	0.00	0.00	*50.00 F
60	1		*Right front rack end / 🎵	0.00	0.00	*50.00 F
61	1		*Right front linkage / 🕅 🖊	0.00	0.00	*65.00 F
62	1		*Right front brake disc cover	0.00	0.00	*145.00 F
63	1		*Right front brake sensor / Th	0.00	0.00	*600.00 F
64	1		*Right frt rim / (V)	0.00	0.00	*55.00 FS
65	1		*Front number plate X	0	0.00	*28.00 FS
66	1		*Coolant 1	U	0.00	
F=Fra	nchise	part, S=SpcNet	t. Sub Total (S\$)			11,887.00
			+ Margin on L,N Items 10.00% (S\$)			1,180.40
			Total Parts (S\$)			13,067.40

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

120.00 680.00 Miscellaneous Items To check & repair wiring. To check under carriage, replace damage parts & assembly. 120.00 1 250.00 2 To check, adjust 4 wheel alignment. 60.00 To remove, radiator, condenser, fill coolant, air con freon. 3 100 150.00 To remove, replace rt frt tyre rim, tyre, balance and assembly. 4 5 To reset ECU. 1,380.00 Sub Total (S\$)

Estimates on Labour	Lab.Typ	e	Amount
Paintwork Labour 1 To respray damaged parts. Labour Items 2 To knock, straighten frt inner, lower, side panels, rt frt wheel hse, rt frt inner wheel hse, rt in her in fet lewer member, left frt wheel hse, rt frt dr, renew frt bonnet, frt support	New	1200 Mars 1800	1,800.00 3,200.00
panel, frt lights, frt fender, frt grille, frt bumper & assembly. Gross Labour	Cost (S\$	3)	5,000.00

Shu Fatt Auto Works/SMF9862J/14/07/2022 13:39. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Stevi (LKK) 15/7/22, 19.00c

00- M/L 18 M 45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No iflegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

CS CamScanner

Amount



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

05/07/2022 15:52 (SGT) Both 05/07/2022 11:15 (SGT) Lower Delta Rd, Singapore junction of Lower Delta Road and Delta Road Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner NRIC No

Email Address Mobile Phone No. Alternative Phone No No

Woo Chee Wai SXXXX687H

SMF9862J

john6646608@yahoo.com.sg (Phone) +65-96646608

VEHICLE PARTICULARS

Manufacturer Model Variant

Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Subaru Forester

Private use

Yes Private car Auto 2000

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

Allianz Insurance Singapore Pte. Ltd. SP2000035725-01

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

Woo Chee Wai SXXXX687H 05/04/1958 Indoor

Accident report SS2Q22750001

Page 1 of 17



03/10/1975 46 YEARS AND 9 MONTHS Date Of Driving Pass Driving experience Male (Phone) +65-96646608 Gender Mobile Number Alt. Phone Number john6646608@yahoo.com.sg Email Address Blk 1 Delta Avenue, #16-41 Address Address complement 160001 Postcode Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Collision - Cross Junction Type of Accident Weather Conditions Road Surface Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Yes Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

See accident statement

ATTACHMENT(S)

Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

SMA293L Vehicle Registration Number Vehicle Manufacturer Toyota Vehicle Model C-hr Vehicle Variant Vehicle Colour Vehicle Category Private hire Name of Driver Ng Lye Heng NRIC No SXXXX827A

Accident report SS2Q22750001

Page 2 of 17



 Contact Number
 (Phone) +65-91122044

 Address

 Address complement

 Postcode

 Insurance Company Name

 Nature Of Damage

 Details of property damaged in accident

 No. Of Passenger (Including Driver)
 3



SKETCH PLAN

Insurer Allianz Veh No.

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful inscrepresentation or withholding of material facts may
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation

- 6. The report will be forwarded by the insurers of the GA Records Management Centre established by the General insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

Funderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data-personal information set cut in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to
- (ii) investigating the accident and/or my claims;
- (a) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers haw firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Driver's Signature (# driver is not the policyholder) / Date Witnessed by Reporting Centre Personnel & Time (ELEND: Sketch Plan A: MY CAR SMF 9862J B: Other Car SMA 1931 GANGES ANENUE

Accident report SS2Q22750001

Page 4 of 17



Describe Circumstances of the Accident
TIME : 21112 HES
DATE : 5 Jeny 2022.
LOCATION: AS SHOWN IN DRAWING
J was chiving streight from Lower Dotta Road towards Dotta Road while crossing the Haffer junction, a white toyota C-He (SAIM While crossing) the Haffer junction, a white toyota C-He (SAIM 231) turning right. How Dotta Road towards Alexandra Road hit me and the other team corrections and the other chiver both me and the other team corrections and the other chart to shock both our condition and nobody in conveyed by the ambulance. My PARILEMENE : WOO CHEE WAI, DRIVER AND POLICY HOLDER (SIRAGEHH) OTHER DRIVER: MR NG LYE HENG (SIRYABETA)

Declaration

W/a declare the foregoing particulars are true in every respect.

Folicy holder's Signature / Date &

Driver's Signature (# driver is not the policyholder) / Cate & Time

Witnessed by Reporting Centre Personnel