

Case Details

Case Reference Number :

TAX/07/22/2025

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6313S

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18778-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 10/07/2022 11:30 AM

Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	<input type="text" value="0"/>	<input type="text" value="0"/>	Not Give <input type="button" value="v"/>	Xan

Total Spare Part Cost 7,812.58

Surveyor Total 1,886.77

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 6,250.06

Final Sur Total 1,509.42

SMRT Recommendation											Surveyor Approval			
COM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	Xan
Standard	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	25.00	932.93	Replace	1	0	Repair	R
Standard	Main			HINGE ASSY, REAR DOOR , UPPER RH	1	83.30	83.30	25.00	62.47	Replace	0	0	Not Give	Xan
Standard	Main			HINGE ASSY, REAR DOOR , LOWER RH	1	73.30	73.30	25.00	54.97	Replace	0	0	Not Give	Xan
Standard	Main			DOOR REAR MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	768.60	768.60	10.00	691.74	Replace	0	0	Not Give	Xan
Standard	Main			DOOR REAR WINDOW REGULATOR SUB-ASSY, RH	1	200.70	200.70	25.00	150.52	Replace	0	0	Not Give	Xan
Standard	Main			CHECK ASSY, REAR DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0	Not Give	Xan
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	618.60	Replace	bf
Standard	Main			PATCH, SIDE PANEL REAR END , RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	Not Give	Xan
Standard	Main			LINER, REAR FENDER , RH	1	135.80	135.80	25.00	101.85	Replace	1	101.85	Replace	de
Standard	Main			WHEEL, DISC	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	1,166.	Replace	cut
Standard	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0	Check	?
Standard	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	1	0	Repair	R
Total Spare Part Cost									7,812.58					
Lump Sum Discount (%)									20.00					
Final Spare Part Cost									6,250.06					
											Surveyor Total		1,886.77	
											Lump Sum Dis (%)		20.00	
											Final Sur Total		1,509.42	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	1,690.00	500.00	
2	Main	TO REPAIR LH PORTION	338.00	0.00	Xan
Total:			2,028.00	500.00	

Cost Detail

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY VIEW MIRROR	180.00	0.00 X11	
2	Main	TO RESPRAY REAR BUMPER	378.00	0.00 X11	
3	Main	TO RESPRAY FLOOR CORNER PANEL RH	180.00	0.00 X11	
4	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 X11	
5	Main	TO RESPRAY REAR FENDER RH	378.00	200.00	
6	Main	TO RESPRAY RH REAR DOOR	378.00	200.00	
7	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00	
8	Main	TO RESPRAY RIM	180.00	0.00 X11	
Total:			2,034.00	500.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	56.00	0.00 X11	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0.00 X11	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40.00	
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00	
5	Main	TO TRANSFER DOOR MECHANISM	120.00	0.00 X11	
6	Main	TO WASH AND VACUUM	60.00	0.00 X11	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 X11	
Total:			776.00	100.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	6,250.06	1,509.42
Total Labour Cost	2,028.00	500.00

5:03 PM

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spray Painting	2,034.00	500.00
Other	776.00	100.00
Overall Total	11,088.06	2,609.42
Lump Sum Repair Option		<input checked="" type="checkbox"/>
Lump Sum Total	11,100.00	2,600.00
Surveyor Approved Amount		2,600.00
No of Repair Days*	8	5
Remarks	-	resurvey after repair photo
Surveyor Name		Rasul
Signature		
		<input type="button" value="Save"/> <input type="button" value="Clear"/>
Survey Date	13/07/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/07/2022 15:23 (SGT)
Reported by	Driver
Date of Accident	10/07/2022 19:30 (SGT)
Exact Location of Accident	Bedok North Ave 1, Singapore
Additional Location Information	BEDOK NORTH AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6313S
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662672
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

DRIVER

Name of Driver	HUANG WENXIONG
NRIC No	SXXXX838A
Date Of Birth	03/10/1984
Occupation	Outdoor

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

18/04/2006

16 YEARS AND 3 MONTHS

Male

(Phone) +65-68662672

AUTO-SVCS-TARC@SMRT.COM.SG

11

-

-

No

RELIEF

No

-

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Side Swipe

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name

Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

No

2

No

-

Yes

1

No

-

-

-

-

-

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

No

No

-

CIRCUMSTANCES OF ACCIDENT

I WAS CROSSING FROM CHAI CHEE STREET GOING TO BEDOK NORTH AVE 1 TRAFFIC LIGHT IN MY FAVOUR WHEN A MOTORCYCLE COLLIDED UNTO THE RIGHT REAR DOOR PASSENGER OF MY TAXI. LEFT SIDE MIRROR COVER DROPPED DUE TO THE IMPACT.

THE AMBULANCE CAME BUT THE RIDER DECLINE IT BECAUSE HE WAS FINE AND NOT INJURED.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

Yes

Yes

FILE TO BIG

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

FBS6926R

-

-

-

-

Vehicle Category	Motorcycle
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
12/07/2022

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan




Describe Circumstance of the Accident

Lined area for describing the accident circumstances.

Declaration

(We declare the foregoing particulars are true in every respect.)



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time
12/2/2 1133am

Witnessed by (Name) / Centre Platform as (Name as in NR QID Card)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHD6313S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS100078
Chassis No.:	JTDKB3FU403573299
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count: -	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$13,828.00
Total Rebate Amount:	\$17,578.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jul 2022

OK