

(08/11/20) wef

REF: NS/INC22006710/Rvc

369K

ASS. REC. BY: *John***ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SHB1281T*at Workshop m/s *STRINGS (SMRT)*of *60,000,000 / 1st PK 24*Insured: SNG 6611U *NTMC*

Policy No. \_\_\_\_\_


Claims No. MT/1179903-002

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *SHB1281T*Yr Regn: *2021 OCT*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MG MG5 EV EXCITE T* c.c. *—*Colour: *GREEN* A/C: Insured / Std / NI / NASp. Reading: *45244* T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *LS JE 24033MG05-7810*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/60R16*R: *—*BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *11/07/22* D.O.I. *13/07/22*Survey held at *STRINGS*Des. of Damages: Frt / Rear / O/S *(N/S)* / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

18/8/22 Rasul informed final fig \$6613.02 (Red 11,734.21, 63%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 22/8/22-typist

Days Of Repair: *6*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format : TP

Lump Sum / I.B.I: (\$ 6613.02)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

## Case Details

Case Reference Number :

TAX/07/22/2023

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB1281T

Company Type : Strides Taxi Pte Ltd

Estimation ID : EST-18784-ID

Assigned By : Taxi Claims Manager

Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd

Accident Date and Time : 11/07/2022 04:30 AM

Vehicle Age(In Months) : -

## Documents / Photographs

View Documents / Photographs

Total Documents: 0

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation |              |         |                 |                               |     |                         |                |        |                 |                 | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|-------------------------------|-----|-------------------------|----------------|--------|-----------------|-----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                     | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard            | Main         |         |                 | FASCIA-RR BPR                 | 1   | 758.48                  | 758.48         | 10.00  | 682.63          | Replace         | 1                 | 0                        | Repair         | R       |
| Standard            | Main         |         |                 | FENDER ASM-FRT - LH           | 1   | 379.80                  | 379.80         | 10.00  | 341.82          | Replace         | 1                 | 0                        | Repair         | R       |
| Standard            | Main         |         |                 | DOOR ASM-FRT SI -L            | 1   | 2,338.76                | 2,338.76       | 10.00  | 2,104.88        | Replace         | 1                 | 2,104.                   | Replace        | bt ✓    |
| Standard            | Main         |         |                 | HINGE ASM-RR S/D UPR-L        | 1   | 46.90                   | 46.90          | 10.00  | 42.21           | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | HINGE ASM-RR S/D LWR-L        | 1   | 47.22                   | 47.22          | 10.00  | 42.50           | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | CHECK ASM-FRT S/D-L           | 1   | 21.01                   | 21.01          | 10.00  | 18.91           | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | REGULATOR ASM-FRT S/D WDO-L   | 1   | 324.06                  | 324.06         | 10.00  | 291.65          | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | MOTOR ASM-FRT S/D WDO REG-L   | 1   | 169.00                  | 169.00         | 10.00  | 152.10          | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | STICKER STRIDES TAXI ( DOOR ) | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace         | 1                 | 60.00                    | Replace        | na ✓    |
| Standard            | Main         |         |                 | DOOR ASM-RR SI -L             | 1   | 2,185.04                | 2,185.04       | 10.00  | 1,966.54        | Replace         | 1                 | 1,966.                   | Replace        | bt ✓    |
| Standard            | Main         |         |                 | HINGE ASM-RR S/D UPR-L        | 1   | 46.90                   | 46.90          | 10.00  | 42.21           | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | HINGE ASM-RR S/D LWR-L        | 1   | 47.22                   | 47.22          | 10.00  | 42.50           | Replace         | 0                 | 0                        | Not Give       | Xan     |
| Standard            | Main         |         |                 | CHECK ASM-RR S/D LH           | 1   | 21.01                   | 21.01          | 10.00  | 18.91           | Replace         | 0                 | 0                        | Not Give       | Xan     |

Total Spare Part Cost 9,323.36

Surveyor Total 4,153.02

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 9,323.36

Final Sur Total 4,153.02

| SMRT Recommendation   |              |         |                 |                                       |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| QM Type               | Costing Type | Portion | Material Number | Part Name                             | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| Standard              | Main         |         |                 | REGULATOR ASM-RR S/D WDO-L            | 1   | 265.30                  | 265.30         | 10.00  | 238.77          | Replace                  | 0                 | 0                        | Not Give       | kan     |
| Standard              | Main         |         |                 | MIRROR ASM-O/S RR VIEW - LH           | 1   | 478.40                  | 478.40         | 10.00  | 430.56          | Replace                  | 1                 | 0                        | Repair         | R       |
| Standard              | Main         |         |                 | PANEL-BODY SI OTR-L                   | 1   | 1,747.82                | 1,747.82       | 10.00  | 1,573.04        | Replace                  | 0                 | 0                        | Not Give       | kan     |
| Standard              | Main         |         |                 | PANEL-BODY SI OTR MID                 | 1   | 323.23                  | 323.23         | 10.00  | 290.91          | Replace                  | 0                 | 0                        | Not Give       | kan     |
| Standard              | Main         |         |                 | PANEL-BODY SI OTR FRT- LH             | 1   | 235.24                  | 235.24         | 10.00  | 211.72          | Replace                  | 0                 | 0                        | Not Give       | kan     |
| Standard              | Main         |         |                 | STICKER ELECTRIC ( LOGO               | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace                  | 1                 | 21.60                    | Replace        | kan     |
| Standard              | Main         |         |                 | WHEEL                                 | 1   | 618.07                  | 618.07         | 10.00  | 556.26          | Replace                  | 1                 | 0                        | Repair         | R       |
| One Time Key In       | Main         |         |                 | HANDLE-FRT S/D O/S - LH               | 1   | 36.92                   | 36.92          | 10.00  | 33.23           | Replace                  | 1                 | 0                        | Repair         | R       |
| One Time Key In       | Main         |         |                 | COVER-FRT S/D LK CYL - LH             | 1   | 14.87                   | 14.87          | 10.00  | 13.38           | Replace                  | 0                 | 0                        | Not Give       | kan     |
| One Time Key In       | Main         |         |                 | PLATE ASM-FRT S/D O/S HDL BKG - LH    | 1   | 32.86                   | 32.86          | 10.00  | 29.57           | Replace                  | 0                 | 0                        | Not Give       | kan     |
| One Time Key In       | Main         |         |                 | WEATHERSTRIP ASM-FRT S/D (DR SI) - LH | 1   | 63.96                   | 63.96          | 10.00  | 57.56           | Replace                  | 0                 | 0                        | Check          | ?       |
| One Time Key In       | Main         |         |                 | WEATHERSTRIP ASM-FRT S/D (BODY SI)    | 1   | 66.56                   | 66.56          | 10.00  | 59.90           | Replace                  | 0                 | 0                        | Check          | ?       |
| Total Spare Part Cost |              |         |                 |                                       |     |                         |                |        | 9,323.36        | Surveyor Total 4,153.02  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                       |     |                         |                |        | 0.00            | Lump Sum Dis (%) 0       |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                       |     |                         |                |        | 9,323.36        | Final Sur Total 4,153.02 |                   |                          |                |         |

**Labour's Cost Detail**

| S.No.  | Costing Type | Job Scope            | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR LH PORTION | 3,600.00                | 700.00                  |         |
| Total: |              |                      | 3,600.00                | 700.00                  |         |

**Spray Cost Detail**

| S.No.  | Costing Type | Job Scope                  | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY FRONT FENDER LH | 428.00                  | 220.00                  |         |
| 2      | Main         | TO RESPRAY FRONT DOOR LH   | 428.00                  | 220.00                  |         |
| Total: |              |                            | 3,060.00                | 1,220.00                |         |

| S.No.         | Costing Type | Job Scope                   | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-----------------------------|-------------------------|-------------------------|---------|
| 3             | Main         | TO RESPRAY VIEW MIRROR      | 230.00                  | 70.00                   |         |
| 4             | Main         | TO RESPRAY FRONT PILLAR LH  | 230.00                  | 0.00 <i>XM</i>          |         |
| 5             | Main         | TO RESRAY REAR DOOR LH      | 428.00                  | 220.00                  |         |
| 6             | Main         | TO RESPRAY CENTRE PILLAR LH | 230.00                  | 0.00 <i>XM</i>          |         |
| 7             | Main         | TO RESPRAY REAR FENDER LH   | 428.00                  | 220.00                  |         |
| 8             | Main         | TO RESPRAY REAR BUMPER      | 428.00                  | 220.00                  |         |
| 9             | Main         | TO RESPRAY RIM              | 230.00                  | 50.00                   |         |
| <b>Total:</b> |              |                             | <b>3,060.00</b>         | <b>1,220.00</b>         |         |

**Other Cost Detail**

| S.No.         | Costing Type | Job Scope                               | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|---------------|--------------|-----------------------------------------|-------------------------|-------------------------|---------|
| 1             | Main         | TO WASH AND VACUUM                      | 60.00                   | 0.00 <i>XM</i>          |         |
| 2             | Main         | TO CHECK WIRING AND SYSTEM FUNCTION     | 120.00                  | 0.00 <i>XM</i>          |         |
| 3             | Main         | TO APPLY RUST-PROOFING ON AFFECTED AREA | 200.00                  | 60.00                   |         |
| 4             | Main         | TO DO WHEEL ALIGNMENT / TYRE BALANCING  | 120.00                  | 60.00                   |         |
| 5             | Main         | TO TRANSFER DOOR MECHANISM              | 240.00                  | 120.00                  |         |
| 6             | Main         | TO REPLACE SUNDRY PARTS                 | 100.00                  | 0.00 <i>XM</i>          |         |
| 7             | Main         | TO CHECK & RESET SYSTEM FUNCTION        | 350.00                  | 150.00                  |         |
| 8             | Main         | ISOLATED OF (EV) (NET)                  | 150.00                  | 150.00                  |         |
| <b>Total:</b> |              |                                         | <b>1,340.00</b>         | <b>540.00</b>           |         |

**Summary**

|                         | Estimator Assesment(\$) | Surveyor Assesment(\$) |
|-------------------------|-------------------------|------------------------|
| Total Spare Part Detail | 9,323.36                | 4,153.02               |
| Total Labour Cost       | 3,600.00                | 700.00                 |
| Total Spray Painting    | 3,060.00                | 1,220.00               |

|                          | Estimator Assesment(\$)                                                           | Surveyor Assesment(\$)                                                              |
|--------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Other                    | 1,340.00                                                                          | 540.00                                                                              |
| Overall Total            | 17,323.36                                                                         | 6,613.02                                                                            |
| Lump Sum Repair Option   |                                                                                   | <input type="checkbox"/>                                                            |
| Lump Sum Total           | 0.00                                                                              | 6,613.02                                                                            |
| Surveyor Approved Amount |                                                                                   | 6,613.02                                                                            |
| No of Repair Days*       | 8                                                                                 | 6                                                                                   |
| Remarks                  | -                                                                                 | resurvey before paint part by part                                                  |
| Surveyor Name            |                                                                                   | Rasul                                                                               |
| Signature                |  |  |
| Survey Date              | 13/07/2022                                                                        |                                                                                     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

|                                 |                              |
|---------------------------------|------------------------------|
| Date of Submission              | 13/07/2022 14:50 (SGT)       |
| Reported by                     | Driver                       |
| Date of Accident                | 11/07/2022 12:30 (SGT)       |
| Exact Location of Accident      | Choa Chu Kang Way, Singapore |
| Additional Location Information | CHOA CHU KANG WAY            |
| Country/State of Loss           | Singapore                    |

## DETAILS OF OWN VEHICLE

|                             |                            |
|-----------------------------|----------------------------|
| Vehicle Registration Number | SHB1281T                   |
| INSURED/POLICYHOLDER        |                            |
| Is company?                 | Yes                        |
| Name Of Registered Owner    | Strides Taxi Pte Ltd       |
| Company Reg No              | 1XXXXX369K                 |
| Email Address               | AUTO-SVCS-TARC@SMRT.COM.SG |
| Mobile Phone No             | (Phone) +65-68662672       |
| Alternative Phone No        | -                          |

## VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | MG                        |
| Model                                                                        | MG5                       |
| Variant                                                                      | -                         |
| Exact purpose for which vehicle was being used at time of accident           | -                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Taxi                      |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1                         |

## INSURANCE COMPANY

|                                   |                                |
|-----------------------------------|--------------------------------|
| Name of Insurance Company         | MS First Capital Insurance Ltd |
| Policy Number / Cover Note Number | D-22099115MFSH                 |

## DRIVER

|                |               |
|----------------|---------------|
| Name of Driver | FOO SIANG KIM |
| NRIC No        | SXXXX817E     |
| Date Of Birth  | 13/03/1948    |
| Occupation     | Outdoor       |

Of Driving Pass  
ing experience  
nder  
obile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

30/08/1966  
55 YEARS AND 11 MONTHS  
Male  
(Phone) +65-68662672  
-  
AUTO-SVCS-TARC@SMRT.COM.SG  
11  
-  
-  
No  
Hirer  
No

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface  
Side Swipe  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### PASSENGER 1

Name UNKNOWN  
Gender Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING ALONG CHOA CHU KANG WAY TOWARDS CHOA CHU KANG ROAD WITH ONE PASSENGER ( FEMALE CHINESE) ON BOARD. SUDDENLY A VEHICLE SNG6611U CAME OUT FROM THE SLIP ROAD WITHOUT STOPPING AT THE STOP LINE AND COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? Yes  
Reasons for not uploading a video of the accident FILE TOO BIG

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SNG6611U

Manufacturer  
Model  
Variant  
Colour  
Category  
Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
Private car  
LEE CHIN MING  
-  
-  
-  
-  
-  
-  
-

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Sketch Plan

Describe Circumstance of the Accident

Lined area for describing the accident circumstances.

Declaration

I/We declare the foregoing particulars are true in every respect



Police Officer's Signature & Date & Time

12-7-22

Driver's Signature (if driver is not the policyholder) & Date & Time

12-7-2022

Witnessed by Reporting Control Personnel  
(as per in NRND 3 lines)

Page 6 of 11

subject

Chlorine Disinfecting  
Wing  $\leftarrow$

12th Street NW

1- Kung's City

CHCA with X-ray WAX

PH 70 STOP  
SN 6611 W  
M15544

22/12/21

> Back to One Motoring

## Enquire PARF/COE Rebate for Registered Vehicle

|                               |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Company                              |
| Owner ID:                     | 369K                                 |
| Vehicle No.:                  | SHB1281T                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 15 Jul 2022                          |
| Vehicle Make:                 | M.G.                                 |
| Vehicle Model:                | MG5 EV EXCITE T                      |
| Primary Colour:               | Green                                |
| Manufacturing Year:           | 2021                                 |
| Engine No.:                   | -                                    |
| Chassis No.:                  | LSJE24033MG057810                    |
| Maximum Power Output:         | 120.0 kW (160 bhp)                   |
| Open Market Value:            | \$29,128.00                          |
| Original Registration Date:   | 01 Oct 2021                          |
| First Registration Date:      | 01 Oct 2021                          |
| Transfer Count: -             | 0                                    |
| Actual ARF Paid:              | \$5,000.00                           |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 30 Sep 2029                          |
| PARF Rebate Amount:           | \$3,750.00                           |
| COE Expiry Date:              | 30 Sep 2029                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 8                                    |
| PQP Paid:                     | \$37,186.00                          |
| COE Rebate Amount:            | \$33,506.00                          |
| Total Rebate Amount:          | \$37,256.00                          |

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Jul 2022

OK