

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22006711/Rqcm4		
75 BRAS BASAH ROAD						
INCOME CENTRESINGAPORE 189557			Date:	18-01-2023		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMJ 1122T	Veh. Ir	spected	SG 5431U	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1179258-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	13/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	VOLVO B9TL 9.4L A	c.c		9364	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	YV3S4P922HA181099	Coloui	ſ	GREEN	
	Odometer	356905	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70R22.5	FALKE	V	8 mm	
	L/H Front Tyre	275/70R22.5	FALKE	V	8 mm	
	R/H Rear Tyre	275/70R22.5 (D/D)	FALKE	N	8/8 mm	
	L/H Rear Tyre	275/70R22.5 (D/D)	FALKE	V	8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/07/2022	Inspec	tion Date	13/07/2022	
	Survey held at	Survey held at STRIDES AUTOMOTIVE SERVICES PL.				
		60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					