



**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 13/07/2022

User ID : JeongCH

**Section A - Accident Details**

Registration Number	SMB1313B
Case Reference Number	BUS/07/22/7005
Registration Date	2/26/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Yeo Ching Heng Simon
Type of Accident	Head to Rear
Accident Date and Time	7/6/2022 2:24 PM
Accident Reported Date and Time	7/6/2022 7:45 AM
Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1313B - Rear left bumper cracked SLT640E (TP) - INSURED WITH NTUC
Prepared Date and Time	7/13/2022 2:10 PM
Chassis Number	WMAA22ZZ7D7001738
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$0.00
Total Spray Cost	\$786.00	\$0.00
Total Spare Part Cost	\$3,185.88	\$0.00
Total Other Cost	\$960.00	\$0.00
<b>TOTAL COST</b>	<b>\$6,521.88</b>	<b>\$0.00</b>
Temp Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	13/07/2022 2:18 PM	
Signature		X
Remarks		

**Section C - Quotation and Accident Invoice Details**

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

**SMRT Accident Vehicle Repair Estimates**

<b>SMRT Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/07/2022

User ID : JeongCH

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	1060
<b>Total Labour</b>	<b>\$1,590.00</b>	

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$786.00	616
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$786.00</b>	

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
ADVERTISEMENT STICKER	\$960.00	
<b>Total Other Costs</b>	<b>\$960.00</b>	

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
010060	Body	F01001-CW271	COVER:REAR TAIL LAMP,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	cm ✓
010064	Body	F01001-CW274	BUMPER:REAR,CENTR E,FOR MAN A22 BUS	1.00	\$1,868.80	10.00	\$1,681.92	Replace	Repair
010463	Body	S01001-CW006	FRAME,REAR BUMPER:FOR MAN A22 BUS	1.00	\$1,423.20	0.00	\$1,423.20	Replace	Repair
<b>Total</b>					<b>\$4,266.70</b>		<b>\$3,982.35</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram

Hp 90010068

3 days

4/8

13/07/22 @ 1710

Resy after repair