



OFFICIAL FERRARI IMPORTER SINGAPORE

Date: 12th July 2022

Ital Auto Pte Ltd**QUOTATION**

To: China Taiping Insurance Pte Ltd
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Our Ref: NA
Reg. No SGN9U
Model F8 SPIDER
VIN: 262120
Mileage:
Terms:

Tel: 63896111 Fax:
email: www.sg.cntaiping.com

Item	Description	Qty	Unit Price Excl. GST	Line Discount	Line Amount Excl. GST
------	-------------	-----	----------------------	---------------	-----------------------

LABOUR

L	TO REPLACE DAMAGED ITEMS	68 70	\$ 1,920.00	130,560	\$ 134,400.00
Sub Total					\$ 134,400.00
Total Amount Include GST:					\$ 143,808.00

SPRAY PAINT PANELS

L	TO SPRAY PAINT DAMAGED PANELS	15	\$ 1,920.00		\$ 28,800.00
Sub Total					\$ 28,800.00
Total Amount Include GST:					\$ 30,816.00

PARTS

P	REFER PARTS LIST (PENDING PRICE FOR ITEMS 188,263,281)	1	\$ 609,222.43		\$ 609,222.43
Sub Total					\$ 609,222.43
Total Amount Include GST:					\$ 651,868.00

Steve (LKK)
15/7/22, 3.30pm

OP- LMK
EXC - ?
PIP
Lg BL y
30 Jy

Grand Total before Tax: \$ 772,422.43**Grand Total Including GST: \$ 826,492.00**

This is an estimate only and does not represent a contract for services. This estimate is based on the scope of the work to be completed for the job as described above. This estimate is based on our evaluation of the requirements necessary to complete the job and does not include material price increases or additional labor and material which may be required should unforeseen problems arise after the work has started. This quotation is valid for thirty (30) days only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

S/N	ABL	REF NO.	Description	Qty	U/PRICE	E/PRICE
1	0065	2	UNDERBODY WATER RETURN PIPE	1	387.04	387.04
2	0065	3	WATER DELIVERY HOSE TO RADIATOR	1	283.55	283.55
3	0065	4	WATER RETURN HOSE FROM RADIATOR	1	247.29	247.29
4	0065	11	COLLAR	12	3.52	42.24
5	0065	29	RADIATOR CONNECTOR HOSE UNION	1	260.40	260.40
6	0065	30	PIPE RETAINER CLIP	1	2.29	2.29
7	0065	34	VENT PIPE FROM RADIATOR TO DISCONNECTER U	1	62.42	62.42
8	0065	36	COLLAR	1	2.92	2.92
9	0065	37	HOSE COLLAR	1	1.40	1.40
10	0071	1	BRAKE FLUID RESERVOIR	1	242.59	242.59
11	0071	4	HOSE COLLAR	4	1.40	5.60
12	0075	1	FRONT SHOCK ABSORBER (21) / OT	222	4773.00	9546.00
13	0075	7	LOWER SPACER / nec	21	26.20	52.40
14	0075	8	FRONT SHOCK ABSORBER SPRING / nec	21	207.80	415.60
15	0075	9	UPPER SPRING SPACER / nec	21	42.69	85.38
16	0075	10	COMPL. SHOCK ABSORBER RETAINER CAP / nec	21	408.50	817.00
17	0075	11	SCREW / nec	4	9.94	39.76
18	0075	12	SHOCK ABSORBER BUSH / nec	21	94.29	188.58
19	0075	16	BALL JOINT / nec	21	298.30	596.60
20	0075	17	SCREW / nec	21	75.83	151.66
21	0076	1	COMPL. LH FRONT HUB CARRIER / OT	1	4861.18	4861.18
22	0076	1	COMPL. RH FRONT HUB CARRIER ?	1	4861.18	4861.18
23	0076	7	COMPL. UPPER LH FRONT ARM / OT	1	2508.82	2508.82
24	0076	7	COMPL. UPPER RH FRONT ARM ?	1	2508.82	2508.82
25	0076	10	THREADED ROD / nec	16	10.37	165.92
26	0076	12	COMPL. LOWER LH FRONT ARM / OT	1	3009.14	3009.14
27	0076	12	COMPL. LOWER RH FRONT ARM ?	1	3009.14	3009.14
28	0077	21	FRONT BRAKE DISC ? / CRA	2	8310.28	16620.56
29	0077	15	SCREW COLLAR / nec	42	21.28	85.12
30	0077	16	BRAKE AIR PIPE / mis	2	190.39	380.78
31	0077	17	RH FRONT BRAKE AIR DUCT / mis	1	626.67	626.67
32	0077	17	LH FRONT BRAKE AIR DUCT / mis	1	626.67	626.67
33	0078	1	STABILISER BAR / OT	1	594.47	594.47
34	0078	5	BALL-JOINT TIE-ROD / OT	1	212.87	212.87
35	0078	6	BALL-JOINT TIE-ROD / OT	1	218.78	218.78
36	0083	1	20" FRONT WHEEL / CH	1	2495.15	2495.15
37	0083	1	20" REAR WHEEL (R-LH) / CH	12	2542.74	5085.48
38	0083	4	TYRE PRESSURE MONITORING SYSTEM WHEEL SE	4	437.32	1749.28
38-A	0083	12	FRONT TYRE (F-LH) - 70 80%	1	1157.93	1157.93
38-B	0083	12	REAR TYRE (R-LH) - 70 80%	12	1300.67	2601.34
39	0085	3	CLOCK SPRING CONTACT / nec	1	1056.83	1056.83
40	0085	9	DRIVER SIDE AIRBAG MODULE / BR	1	4584.56	4584.56
41	0086	1	STEERING BOX / OT	1	10689.46	10689.46
42	0086	12	GASKET / nec	2	2.51	5.02
43	0087	22	GASKET / nec	2	2.55	5.10
44	0087	23	UNDERBODY POWER STEERING RETURN PIPE	1	171.43	171.43
45	0087	24	CLIP / nec	1	1.62	1.62
46	0087	25	COLLAR / nec	3	5.28	15.84
47	0095	1	FRONT BUMPER MOUNTING CROSS-MEMBER	1	4379.11	4379.11

/ mis
 / mis
 / mis
 / nec
 / mis
 / mis
 / mis
 / nec
 / mis
 ?
 / nec

/ nec

/ TA

/ BR

48	0095	6	RH FRONT SPAR (charm L ₁) - BT	1	1801.62	1801.62	
49	0095	7	LH FRONT SPAR (" " - BT	1	1754.51	1754.51	
50	0095	9	RIVET - ncc	62	3.48	215.76	
51	0095	10	ANGULAR BRACE FOR RH STRUT - BT	1	336.39	336.39	
52	0095	11	ANGULAR BRACE FOR LH STRUT - BT	1	336.39	336.39	
53	0095	13	FRONT RH SHOCK TOWER - BT	1	18943.40	18943.40	
54	0095	15	COMPL. LOWER FRONT SUSPENSION CROSS MEM	1	1509.14	1509.14	- BT
55	0095	16	RH BRACKET - BT	1	273.48	273.48	
56	0095	18	RH FRONT ACCELEROMETER BRACKET - BT	1	72.24	72.24	
57	0095	19	LH FRONT ACCELEROMETER BRACKET - BT	1	72.24	72.24	
58	0095	20	BRACKET - BT	2	232.44	464.88	
59	0095	29	FRONT LH TORQUE BOX - BT	1	4910.07	4910.07	
60	0095	30	COMPL. RH FRONT WHEEL BAY COVER PANEL	1	1049.66	1049.66	- BT
61	0095	31	COMPL. LH FRONT WHEEL BAY COVER PANEL	1	1174.31	1174.31	- BT
62	0095	32	COMPL. RH UPPER FRONT DIAGONAL BRACE	1	743.85	743.85	- BT
63	0095	33	COMPL. LH UPPER FRONT DIAGONAL BRACE	1	743.85	743.85	- BT
64	0095	36	RH DIAGONAL WINDSCREEN VALENCE PANEL END	1	1268.96	1268.96	- BT
65	0095	37	LH DIAGONAL WINDSCREEN VALENCE PANEL END	1	1268.96	1268.96	- BT
66	0095	38	WINDSCREEN VALENCE PANEL CROSS MEMBER	1	2136.45	2136.45	- BT
67	0095	39	RH WINDSCREEN VALENCE PANEL FASTENER BRA	1	444.15	444.15	- BT
68	0095	40	LH WINDSCREEN VALENCE PANEL FASTENER BRA	1	444.15	444.15	- BT
69	0096	5	COMPL. UPPER LH HINGE REINFORCEMENT	1	919.12	919.12	- BT
70	0096	10	COMPL. LOWER LH HINGE REINFORCEMENT	1	766.42	766.42	- BT
71	0096	20	LH B-PILLAR TRUSS	1	840.12	840.12	- BT
72	0096	24	LH SUBFRAME CONNECTOR CRASH BOX	1	6011.68	6011.68	- BT
73	0096	30	LOWER RH DIAGONAL BRACE CONNECTED TO TU	1	479.76	479.76	- BT
74	0096	31	LOWER LH DIAGONAL BRACE CONNECTED TO TU	1	479.76	479.76	- BT
75	0096	33	RH TUNNEL UPPER FRONT DIAGONAL BRACE	1	708.85	708.85	- BT
76	0096	38	LH CENTRE SIDEWALL	1	36359.45	36359.45	- BT
77	0096	42	LH A-PILLAR TRUSS	1	480.55	480.55	- BT
78	0096	50	LH SKILLET MOUNTING BRACKET	1	287.66	287.66	- BT
79	0096	51	RH LOWER FRONT SUSPENSION CROSS-MEMBER	1	84.07	84.07	- BT
80	0096	52	LH LOWER FRONT SUSPENSION CROSS-MEMBER	1	84.07	84.07	- BT
81	0096	54	FRONT BRACKET FASTENING LH REAR FLANK TO C	1	323.67	323.67	- BT
82	0098	2	LH FLANK (re Fnl)	1	35605.90	35605.90	- 00
83	0098	3	FRONT RH FENDER	1	10763.98	10763.98	- 00
84	0098	4	FRONT LH FENDER	1	10763.98	10763.98	- 00
85	0098	5	COMPL. LH SIDE CONNECTION EXTENSION	1	480.58	480.58	- 00
86	0098	6	COMPL. REAR SPOILER	1	13080.69	13080.69	- 00
87	0099	1	WINDSCREEN SURROUND (LH FH-)	1	5526.61	5526.61	- 00
88	0099	3	RIVET - ncc	2	5.79	11.59	
89	0099	4	RH UPPER PILLAR - 00	1	3123.72	3123.72	
90	0099	5	LH UPPER PILLAR - 00	1	3123.72	3123.72	
91	0099	6	COMPL. UPPER WINDSCREEN CROSS MEMBER	1	1081.31	1081.31	- 00
92	0099	7	SCREW - ncc	4	4.97	19.88	
93	0101	1	COMPL. FRONT BUMPER CARRIER TUBE (whol up)	1	976.24	976.24	- BT
94	0101	2	COMPL. RH FRONT SUBFRAME	1	1670.02	1670.02	- BT
95	0101	3	COMPL. LH FRONT SUBFRAME	1	1670.02	1670.02	- BT
96	0101	4	RH FENDER BRACKET EXTENSION	1	841.00	841.00	- BT
97	0101	5	LH FENDER BRACKET EXTENSION	1	841.00	841.00	- BT

148	0114	2	CENTRAL UNDERBODY SHIELD, FRONT SECTION	1	367.37	367.37
149	0114	3	SCREW	14	8.99	125.86
150	0115	1	COMPL. REAR UNDERBODY SHIELD	1	1236.45	1236.45
151	0115	13	RIVET	8	1.70	13.60
152	0115	26	RH BRAKE AIR INTAKE	1	228.29	228.29
153	0115	27	LH BRAKE AIR INTAKE	1	228.29	228.29
154	0116	1	RH FRONT WHEELHOUSE	1	1050.39	1050.39
155	0116	2	LH FRONT WHEELHOUSE	1	1050.39	1050.39
156	0116	3	SCREW	33	1.59	52.32
157	0121	1	COMPL. UPPER PART OF RH FRONT SEMI-DUCT	1	612.74	612.74
158	0121	2	COMPL. UPPER PART OF LH FRONT SEMI-DUCT	1	612.74	612.74
159	0121	3	FRONT DUCT FOR RH LOWER LATERAL AIR VENT	1	29.27	29.27
160	0121	4	FRONT DUCT FOR LH LOWER LATERAL AIR VENT	1	68.91	68.91
161	0121	5	SCREW	10	7.04	70.40
162	0121	6	SCREW	5	1.62	8.08
163	0121	7	RH UPPER BRAKE COOLING DUCT	1	101.23	101.23
164	0121	8	LH UPPER BRAKE COOLING DUCT	1	101.23	101.23
165	0121	9	COMPL. RH BRAKE AIR INTAKE	1	6951.02	6951.02
166	0121	10	COMPL. LH BRAKE AIR INTAKE	1	6951.02	6951.02
167	0121	11	SCREW	6	2.23	13.36
168	0121	12	CLIP	4	12.96	51.84
169	0121	13	RH HEADLIGHT FASTENER BRACKET	1	61.99	61.99
170	0121	14	LH HEADLIGHT FASTENER BRACKET	1	61.99	61.99
171	0121	15	BRACKET WITH COLLAR	4	2.93	11.71
172	0121	16	SCREW	4	2.88	11.52
173	0121	16	SCREW	8	1.71	13.66
174	0121	17	COMPL. RH HEADLAMP GUIDE	1	26.50	26.50
175	0121	17	COMPL. LH HEADLAMP GUIDE	1	26.50	26.50
176	0121	18	SCREW	2	2.33	4.66
177	0124	1	COMPL. WINDSCREEN	1	6840.14	6840.14
178	0124	2	BLOCK	2	8.68	17.36
179	0124	3	ADHESIVE FOAM	2	12.92	25.84
180	0128	1	FOIL FLAP	2	108.03	216.07
181	0128	2	COMPL. LH AIRBAG	1	1801.92	1801.92
182	0128	13	COMPL. UPPER LH DOOR PANEL -CONFIGURATIO	1	9391.54	9391.54
183	0128	15	LH DOOR INNER CORNER TRIANGLE TRIM	1	77.72	77.72
184	0128	18	LH UPPER DOOR CARD -CONFIGURATION PART	1	951.72	951.72
185	0128	25	COMPL. LH DOOR PANEL -CONFIGURATION PART	1	5862.73	5862.73
186	0128	29	LH DOOR CARD -CONFIGURATION PART	1	8511.91	8511.91
188	0128	31	COMPL. LH DOOR PANEL POCKET-CONFIGURATIO	1	0.00	0.00
189	0129	1	LH EXTERNAL DOOR HANDLE	1	600.24	600.24
190	0129	2	SCREW	2	1.55	3.10
191	0129	3	LH DOOR HANDLE SEAL	1	47.60	47.60
192	0129	4	LH OUTER DOOR HANDLE MODULE	1	412.40	412.40
193	0129	5	EXTERNAL DOOR HANDLE SPACER	2	16.13	32.26
194	0129	6	EXTERNAL DOOR HANDLE SPACER	2	8.66	17.32
195	0129	10	LH DOOR LOCK	1	272.05	272.05
196	0129	18	LH WATERPROOF MEMBRANE	1	104.68	104.68
197	0129	21	DOOR LOCK STRIKER PLATE	2	32.17	64.34
198	0129	28	DOOR CHECK STRAP	1	98.89	98.89

- M U

- H C

- M I S

- H C

- M I S

- M I S

- T N

- M I S

- H C

- M I S

- M I S

- M I S

- M I S

- H C

- H C

- M I S

- M I S

- M I S

- M I S

- H C

- H C

- M I S

- M I S

- H C

- H C

- H C

- H C

- H C

- H C

- H C

- B R

- H C

- H C

- H C

- B R

- B R

- B R

- B R

- B R

- B R

- B R

- P V T

- H C

- H C

- H C

- H C

- H C

- J o u r n a l

- H C

- H C

- H C

- B R

- B R

- B R

- B R

- B R

- B R

- B R

- B R

300	0171	1	"SQUADRA CORSE" SHIELD BADGE	2	1872.79	3745.58
301	0171	2	NUT	6	4.61	27.66
302	0171	3	WASHER	6	1.34	8.04
303	0172	1	COMPL. LH UNDERDOOR TRIM	1	3605.68	3605.68
304	0173	1	COMPL. CENTRE COSMETIC COVER (luggage type)	1	7929.48	7929.48
305	0173	3	VIBRATION DAMPER	2	68.89	137.78
306	0173	4	COMPL. RH COSMETIC TRIM	1	4565.45	4565.45
307	0173	5	SCREW	4	5.03	20.12
308	0173	6	PLUG	2	1.85	3.70
309	0173	7	COMPL. LH COSMETIC TRIM	1	4565.45	4565.45
310	0173	8	SCREW	6	1.51	9.06
311	0173	9	BLOCK	6	1.40	8.40
312	0173	11	COMPL. RH UNDERWINDSCREEN TRAY	1	6728.03	6728.03
313	0173	12	UPPER AIR DUCT SEAL	1	12.84	12.84
314	0173	15	COMPL. LH UNDERWINDSCREEN TRAY	1	6728.03	6728.03
315	0173	16	STABILUS GAS STRUT	2	110.62	221.25
316	0173	17	LH UNDERWINDSCREEN TRAY PLUG	1	24.00	24.00
317	0173	18	WASHER	8	1.30	10.40
318	0173	19	FRONT FIREWALL VENTILATION FLAP	4	5.64	22.56
319	0173	20	RH LUGGAGE COMPARTMENT SEAL	1	270.34	270.34
320	0173	21	LH LUGGAGE COMPARTMENT SEAL	1	270.34	270.34
321	0180	1	HIGH TONE HORN	1	143.00	143.00
322	0180	2	LOW TONE HORN	1	143.00	143.00
323	0180	3	FRONT CRASH SENSOR	2	90.35	180.70
324	0180	5	ACCELEROMETER FOR MAGNERIDE SYSTEM	3	547.26	1641.78
325	0180	6	LATERAL CRASH SENSOR	2	90.59	181.18
326	0180	7	LATERAL CRASH SENSOR	2	90.35	180.70
327	0181	9	AIRBAG ECU	1	1083.66	1083.66
328	0184	1	RH HEADLAMP	1	7106.22	7106.22
329	0184	2	LH HEADLAMP	1	7106.22	7106.22
330	0184	3	SCREW	8	2.88	23.04
331	0184	4	WASHER	8	1.71	13.68
332	0184	5	WASHER	12	1.43	17.16
333	0184	6	COMPL. LATERAL TURN INDICATOR	2	174.48	348.96
334	0184	8	CENTRAL CEILING LIGHT UNIT	1	2233.84	2233.84
335	0184	10	OUTER LH TAILLIGHT	1	1506.88	1506.88
336	0184	12	INNER LH TAILLIGHT	1	1522.74	1522.74
					S\$	609222.43

- nec
 - nec
 - nec
 - BR
 - mis
 - mis
 - mis
 - nec
 - nec
 - mis
 - nec
 - nec
 - mis
 - nec
 - nec
 - mis
 - mis
 - mis
 - nec
 - nec
 - nec
 - mis
 - mis
 - mis
 - mis
 - mis
 - nec
 - BR
 - BR
 - nec
 - nec
 - nec
 - mis
 - BR
 - BR
 - BR

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 29/06/2022 17:54 (SGT)
Reported by Both
Date of Accident 28/06/2022 17:00 (SGT)
Exact Location of Accident Second Link Bridge, Second Link Expy, Kampung Tiram, 81550
Gelang Patah, Johor, Malaysia
Additional Location Information TOWARDS SINGAPORE
Country/State of Loss Malaysia

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGN9U
INSURED/POLICYHOLDER
Is company? No
Name Of Registered Owner KE ZHENGHUI
NRIC No SXXXX793G
Email Address JON.ZHKE@GMAIL.COM
Mobile Phone No (Phone) +65-91712271
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Ferrari
Model F8 SPIDER
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 3902

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number DMPCSNW00066032200

DRIVER

Name of Driver KE ZHENGHUI

Indoor
20/04/2012
10 YEARS AND 2 MONTHS
Male
(Phone) +65-91712271
-
JON.ZHKE@GMAIL.COM
27 WEST COAST PARK #01-01
-
S127720
Yes
-
No
-
-

Type of Accident	Weather Conditions	Road Surface
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

Collided into Property
Raining
Wet

Was any foreign vehicle involved in the accident?	
Number of vehicles involved in the accident	
Was anybody injured in the Accident?	
Was any injured conveyed to hospital by ambulance?	
Was any other vehicle or property damaged?	
Number of Passengers (Including Driver)	
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	
Translator's name	
Translator's ID	
Translator's phone number	
Translator's email	
Original language used in the statement	

No
1
Yes
No
Yes
1

No
-
-
-
-
-

Was the accident reported to the police?

Police Station Name

Police Station Phone No

Alt. Police Station Phone No

Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

Yes
Jurong East Neighbourhood Police Centre
(Phone) +65-18008999999
(Fax) +65-66655791
No. 92 Boon Lay Way Singapore 609962
No
-

REFER TO POLICE REPORT

Are accident photos available for attachment? ☐

Was there any video captured by Car Camera? ☐

Yes
No

Vehicle Registration Number _____
Vehicle Manufacturer _____

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* Refer Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Annex D

NOTICE OF REPORTING

This is to confirm that Ke Zhenghui, NRIC/FIN S8437793G, has reported to the Police an accident which Occurred in Malaysia along Second Link Expressway on 28/06/2022 at 1700hrs involving the following vehicles:

V1 / Complainant's - SGN9U

V1 was entering Singapore through Tuas Checkpoint, while driving along Second Link Expressway, V1 self-skidded to the right and collided against a barrier. V1's vehicle is completely damaged.

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Jurong East
Neighbourhood Police Centre
No 92 Boon Lay Way
Singapore 609962
Tel : 1800-899999

Sgt 122 2311 Saiyidah

29/6/22 1500hrs

Rank/Name of Issuing Officer: SGT Saiyidah

Date: 29/06/2022 Time: 1500hrs

S/D Ref: 32

Police Post/Unit : Jurong East NPC

Original - to be issued to informant

Duplicate - to be submitted to Traffic Police













ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN 94Yr Regn: 5/2/21Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ferrari F8 Spider c.c. 3902Colour: Blue A/C: Insured / Std / NI / NASp. Reading: N/A T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2FF93LMC00026.2170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / STD A/Rim orTyre Size: F: 245/35 ZR 20R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 5 mmR/Bal. 5 mmL/Bal. 5 mmL/Bal. 5 mmD.O.A. 75/6/21D.O.I. 15/7/22Survey held at Ital AutoDes. of Damages: Fit / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Beyond economical repair Total loss

Date / Time Action / Instruction

MV - 1156.000

PV - 516.732

NY - 693.168

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL