

Cheng Hoe Motor Pte Ltd

Blk 1019, Vishnu Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

YN2245C

TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 10/07/2022
TP Veh Reg No: SMC1834J

Estimate No: ES2300007/YISHUN
Date: 04 Jan 2023
Policy No: Z/21/VC00/112555
Veh Reg No: YN2245C
Make/Model: ISUZU ISUZU
FR90SUQA-C
Chassis No: JALFR907B7000031
Engine No: 4HK1888238
Reg. Date: 26/04/2011

Estimate Repair Cost to Vehicle No : YN2245C

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT LH DOOR LAMP	50.00	1 PC	50.00	✓
2 FRONT LH DOOR LAMP HOUSING	45.00	1 PC	45.00	✓
3 FRONT LH SIGNAL LAMP	90.00	1 PC	90.00	✓
4 HEADLAMP LH	280.00	1 PC	280.00	✓
5 HEADLAMP LH LOWER COVER	10.00	1 PC	10.00	X
6 FRONT BUMPER	839.00	1 PC	839.00	✓
7 FRONT LH CORNER PANEL	213.00	1 PC	213.00	✓
8 FRONT LH MUDGUARD	186.00	1 PC	186.00	✓
9 FRONT LH STEP PANEL	159.00	1 PC	159.00	✓
10 FRONT LH DOOR	1,204.00	1 PC	1,204.00	✓
11 FRONT LH DOOR LOWER RUBBER	29.00	1 PC	29.00	X
12 FRONT LH DOOR PROTECTOR	223.00	1 PC	223.00	✓
			3,328.00	
		Less 15%	499.20	2,828.80
Labour				
13 REMOVE AND REPLACE FRT BUMPER ASSY, LH HEADLAMP, SIDE LAMP, MUDGUARD, MUDFLAP, FRT LH DOOR, PROTECTOR AND GARNISH, FRT LH STEP TRAY, KNOCK & REPAIR FRT BUMPER LH BRACKET AND REALIGN THE SAME	650.00	1 LA	650.00	500
14 PUTTY & RESPRAY ON FRT BUMPER, FRT LH DOOR, FRT LH CORNER PANEL, FRT LH DOOR PROTECTOR	800.00	1 LA	800.00	700
15 TO REWRITE ADVERTISEMENT	350.00	1 LA	350.00	250
16 RUSTPROOFING	30.00	1 LA	30.00	✓
17 REMOVE & REFIX FRT LH DOOR GLASS	80.00	1 LA	80.00	✓
			1,910.00	1,910.00
		Total	SS 4,738.80	

Add GST @ 8% 379.10

Total Amount Payable **SS 5,117.90****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/07/2022 19:07 (SGT)
Reported by Driver
Date of Accident 10/07/2022 17:25 (SGT)
Exact Location of Accident Singapore
Additional Location Information OLD CHOA CHU KANG ROAD
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YN2245C
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner OR KIM PEOW CONTRACTORS (PTE) LTD
Company Reg No 1XXXXX891R
Email Address annie@okph.com
Mobile Phone No (Phone) +65-83671960
Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Isuzu
Model FRR90SUQA-C
Variant
Exact purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? Employment
Vehicle Category Yes
Transmission Commercial vehicle
CC Manual
5193

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Policy Number / Cover Note Number Z/21/VC00/112555

DRIVER

Name of Driver VELU ASAITHAMBI
Passport No/FIN FXXXX696Q
Date Of Birth 14/08/1977
Occupation Outdoor

Accident report SC1I227C0002

Page 1 of 16

Name
Gender WORKER
Male

Accident report SC1I227C0002


Page 2 of 16

Describe Circumstance of the Accident

** NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy () Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



A: YN2245C

B: SMC1834J

Seow Joo Hong

(Xiao Yuhong)

S723617B

I was travelling straight on the extreme right lane along Old Choa Chu Kang Road. Out of sudden car B who was driving in the middle lane cut into my lane abruptly without warning. I stamped on my brake but could not avoid the collision and my vehicle skidded towards the center kerb but luckily I managed to stop in time and didn't hit onto the kerb. Next I called for Traffic Police and ambulance assistance but no one was conveyed to hospital. Police officer advised need not do any police report as there was no one injured.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel
(Name as in NPIC card)

(45)

12/2/22