| AS | SIGNMENT |
|--|---|
| From: Date: | C(H 26) 8 0 Ma |
| Estimated Cost; | Type M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / |
| OD / TP/WS/TP RES / OD RES / EVA / INV / MV | Truck / Trailer or |
| To Inspect Vehicle No: | T 0 C 1090 |
| | Make: Tople Cany c.c 1998 |
| at Worlshop m/s | Colour Black . A/C: Insured / Std / NI / NA |
| of | Sp.Reading /9835 4 T/Radio: Insured / Std / NI / NA |
| Insured | Eng/No: |
| Policy No. | C/No: MROS3 BK41070 444,20 |
| Claims No. | Gen. Cond. Good / Fair / Poor / Burnt |
| Sum Insured: Excess: | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inorder / Jammed / Leaked / Burnt or |
| Make of Veh: | Modi: Nil / S/Rim / STD A/Rim or |
| | Tyre Size: F: 215/60R/6- |
| (Policy Condition) | R: 215/60R16 |
| Remark The veh had commenced its N/S O/S repair at the time of inspection. | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / |
| | TOYO/YOKO or Westlake. |
| Bal. or Market Value: | Front Rear |
| IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No | R/Bal. mm R/Bal. 06 mm |
| | L/Bal. 06 mm L/Bal. 06 mm |
| Est. Repairs:days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No | D.O.A. D.O.I. 15/04/22 |
| 2011 3011. 70 3 Val 163 01 NO | Survey held at HD ?e bect. |
| CA / REV / REP. / 24 HRS Vehicle: IN / OU | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or |
| Date: Person Contacted: | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time Action / Instruction | 1 1 |
| TP 1st Cap. | COE Expiny: 31/03/29. |
| | |
| M./ | |
| MV: | |
| Nett: | |
| 7101 | |
| | |
| Note The Para Local | eg, issue describit en crissociales |
| Preli. Report | Days Of Repair: |
|) : Final Report Date/Time, File Return to? | Resurvey No. of Trip: Survey Fee: |
| pater i me, riie Return to? Add Fe | Transportation: |
| aco He | 30: Site Insp (\$)_s+Rs_s |
| 7 | : Interview (\$) Photos |



SINGAPORE ACCIDENT STATEMENT

Accident Details

| Who reported the accid | ent? Own | er (Driver)/ Bot | h |
|--|--------------------------------|------------------------------|-----------------|
| Date of Accident: | 14/07/2023 | 2_ | |
| Time of Accident: | 2:10 | | (AM /PM) |
| Location of Accident: | Hougang Avenue & | towards Ho | ougang Avenue 7 |
| Country/State of Loss: | Singapo | ove | |
| Type of Accident: | Side - to - Side | | |
| Weather Condition: Cle | ar/ Raining | Road Surface | : Dry/ Wet |
| If Not in List, please spe | cify | | |
| Are you claiming under policy for repair to your | | Yes / No | |
| If No, please state action | n to be taken | third Party / F | Reporting Only |
| Was any foreign vehicle | involved in accident? | Yes /No | |
| If yes, please state Vehic | cle No & Vehicle Type: | _ | |
| No. of vehicles Involved | in the accident (include o | own vehicle) <u></u> | 2 |
| Has the driver been appaced accident claims assistan | proached by unknown per ce? | rson(s) soliciting Yes No | offering/ |
| Was the accident report | ted to the police? | Yes / No | |
| If yes, police station nar | me: | | |
| Was notice of Prosecuti | on given? | Yes /No | |
| If yes, against whom? | | | |
| <u>Files</u> | | | |
| Are accident photos ava | ailable for attachment? | Yes No | |
| Was there any video ca | ptured? | Yes / No | |
| Was there any audio ca | ptured? | Yes /No | |

| Details of Own Vehicle | |
|-----------------------------|---|
| Vehicle Registration No: | SLH262B |
| Vehicle Category: | В |
| Vehicle Manufacturer: | Toyota Vehicle Model: Camry |
| Transmission: | Manual / Auto Cc: 2.0 |
| Exact purpose for which | vehicle was being used at the time of accident: |
| Private | Car (Private Use) Employment |
| No. of passengers (include | ding driver) 0 |
| Passenger Name: | |
| Gender: | Male / Female |
| Passenger Name: | |
| Gender: | Male / Female |
| | |
| Own Vehicle Policy | |
| Handling Insurer: | NTUC |
| Coverage Type: ACT / (| Comprehensive / Third Party / Third Party, Fire & Theft |
| Fleet Policy: | Yes /No |
| Registered Owner Name | : Swee Heng Motor Leasing Pte. Ltd. |
| ID Type: | UEN/ NRIC / Passport or FIN / Work Permit |
| Registered Owner ID: | 201827189W |
| Email: | Sweehengmotortrading agmail.com |
| Mobile No: | 9889 5558 |
| Alt. No Type: | Home / Office / Not in List |
| If Not in List, please spec | cify |
| Owner Alt Phone No: | |

Driver's Information

| Is the driver the policy holder? | Yes /No |
|---|--------------------------------------|
| Name of Driver: | Ong Jun Kiat Benedick |
| Gender: | Male)/ Female |
| ID Type: | NRIC / Passport or FIN / Work Permit |
| Driver's ID: | S9522069Z |
| Date of Birth: | 25 06 1995 |
| Driving Pass Date: | 03/02/2016 |
| Mobile No: | 8588 5141 |
| Email: | |
| Address 1: | BLK 632B Senja Road #02-127 |
| Address 2: | Postal Code: _672632_ |
| Occupation: | Indoor (Outdoor) |
| Driver Owner Relationship | Leasing |
| Does Driver own other vehicle | es? Yes No |
| If yes, please provide Vehicle F | Registration No: |
| Handling Insurer: | |
| | |
| TP Vehicle or Property | |
| Was there any other vehicle o | r property damaged? (Yes)/ No |
| If yes, please provide: | |
| (i) Vehicle Registration(ii) Vehicle Category:(iii) No. of passengers (in | No: SG6324P |
| Passenger Name: | |
| Gender: Male / Fen | nale |

| Translation |
|--|
| Was the Sketch Plan Statement translated from another language? |
| Yes No |
| Name of Translator: |
| ID Type: NRIC / Passport or FIN / Work Permit |
| Phone No: |
| Email: |
| What is the original language used in the statement? |
| English / Mandarin / Malay / Tamil / Others: |
| Please attach the following documents: |
| Original report in original language Translated report to English |
| Injured Person's Details |
| Was anyone injured in the accident? Yes/No |
| Any injured conveyed to hospital by Ambulance? Yes /No |
| If yes, please provide: |
| (i) Name: Ong Jun Kiat Benedick |
| (ii) Gender: Male / Female (iii) Injured Person in which Vehicle? SLH 262B |
| (iii) Injured Person in which Vehicle? |
| |
| |
| Witness Details |
| |
| Was there any witnesses? Yes /No |
| Vias there any managed |
| Was there any witnesses? If yes, please provide: Witness Name: |

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be lectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Taking helder la Signature / Date %


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

8 SUA SURFULCH



venicle A: SCH262B Venicle B: SG6324P

| escribe Circumstances of the Accident |
|--|
| |
| On 14.07.2022 at about 14:10 hours along Hougang Avenue 8 towards Hougang Avenue 7, I was travelling straight on lane 2 (left lane) at the above mentioned location and suddenly vehicle (B) from lane 1 make a lane change abruptly into my lane hence collided onto the front right hand side portion of my vehicle (A). |
| Vehicle (A): SLH 262B Vehicle (B): SG 6324P |
| |
| |
| |
| |
| |
| |
| |
| |

Declaration

I/We declare the foregoing particulars are true in every respect.



