



Your Ref: CTI 2022. 9690/ct

Date: 04th Aug 2022

Our Ref: CS1/LAW22006751/Tqy3e2

M/s Just Law LLC

101 Cecil Street #12-12

Tong Eng Building

Singapore 069533

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: WC 7966D

INSURED VEHICLE: EXCAVATOR

ACCIDENT DATE: 14/10/2019

We thank you for your instruction on 13/07/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of WC 7966D from M/s New Auto Spec Appraisal.
- b) Final Repair Bill of WC 7966D from M/s Multilateral Services.
- c) Colour damaged vehicle photographs of WC 7966D.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: WC 7966D
Make & Model	: Isuzu CHY52S
Chassis Number	: JALCYH52SE7000029
Year of Registration	: 2014

2. We recommend that the repairs of the entire damage require about 20 (Twenty) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.