


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. **S2M03TKZ**
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: **7k**
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs. **4** days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: **FBA8866** Yr Rogn: **25/1/06**
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Primo Mover /
 Truck / Trailer or
 Make: **Honda Cb100** c.c. **399**
 Colour: **White** NC: Insured / Std / NI / NA
 Sp. Reading: **not given** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **SH2NC3995SM100022**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SIRIm / STD A/RIm or
 Tyre Size: F: **120/60ZR17**
 R: **120/60ZR17**
 BS / DUH / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /
 TOYO / YOKO or
 Front R/Bal. **6** mm Rear R/Bal. **6** mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. **16/2/22** D.O.I. **23/2/22 1600**
 Survey held at **Wing Fuat**
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: 7k
	rebate: 1402
	MV: 5598
	rr: 2.5k-3k
09/03/22 @ 12.51pm	revised to Stacey Ng via Smart Claims.
09/03/22	Submit PRS.
13/09/22	Submit LS \$6000, 4 days. (Red \$500, 8%)

Date/Time File Press b? : Prel. Report
 13/09 Typist : Final Report
 Date/Time File Return b?

Days Of Repair: **4**
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Wheel and _____

Survey Fee:	
Transportation:	
_____ S + RS. _____ SI	
Fuel/As	
Others	
Total	

Request Fee/Ins: **TP**
6000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8022

Vehicle Details

Vehicle No.: FBA886G
Vehicle to be Exported: No
Intended Deregistration Date: 08 Mar 2022
Vehicle Make: HONDA
Vehicle Model: CB400
Primary Colour: Black
Manufacturing Year: 2005
Engine No.: 2005
Chassis No.: NC23E3000023
Maximum Power Output: JH2NC39955M100022
Open Market Value: -
Original Registration Date: \$7,119.00
First Registration Date: 25 Jan 2006
Transfer Count: 25 Jan 2006
Actual ARF Paid: 7
Intended PARF Rebate Amount: \$1,068.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Feb 2025
COE Category: D - Motorcycle
COE Period(Years): 10
PQP Paid: \$4,383.00
COE Rebate Amount: \$1,402.00
Total Rebate Amount: \$1,402.00

The information contained herein is correct as at 08 Mar 2022

OK

dp: 200

200 x 36

= 7200

= 7k

7000 - 1402

= 5598

Brand	Honda
Model	Honda CB400 Super 4 Spec 3
Engine Capacity	399cc
Classification	Class 2A
Registration Date	12/01/2005
COE Expiry Date	31/12/2024 (2 years 9 months left)
Mileage	-
No. of owners	-
Type of Vehicle	Street Bikes

SGD \$7200

Honda CB400 Super 4 Spec 3 For Sale.
 Coe Till Dec 2024.
 Good Condition.
 Loan Available. Welcome Trade In.
 Read more 



Similar Bikes

View More



04/01/2022

Used Bike

★ Soon Hin Motors Pte...
 Honda CB400 Super 4...
 Pre Own Honda CB400 Spec 3 Fo...

\$8800

♡ 2



09/01/2022

Used Bike

★ Direct Seller
 Honda CB400 Super 4...
 Honda CB400 Super 4 Spec 3 Fo...

\$7500

♡ 3