

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



AUTOMOBILE INSPECTION REPORT



		AUTOMOBILE INSI	PECTI	ON KEPOK I		
INCO	OME INSURANCE	LTD	Ref:	NS/INC22006757/Rce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	14-09-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SGX 2525E	Veh. Ir	nspected	SHC 4882J	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1179886-002	Exces	s (\$)	0.00	
	Assign From		Assigi	n Date	14/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS TAXI (SMRT)	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2015	
	Chassis No.	JTDKN36U905766382	Colou	r	MAROON	
	Odometer	896629	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	SAILUN		6 mm	
	L/H Front Tyre	195/65 R15	SAILUN		6 mm	
	R/H Rear Tyre	195/65 R15	SAILUN		6 mm	
	L/H Rear Tyre	195/65 R15	SAILUN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/07/2022		tion Date	14/07/2022	
	Survey held at	•				
	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.						
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					