





## Case Details

**Case Reference Number :**

TAX/07/22/2038

**Type of Repair :** Accident Repair

**Vehicle Registration Number :**

SHB5792J

**Company Type :** Strides Taxi Pte Ltd

**Estimation ID :** EST-18815-ID

**Assigned By :** Taxi Claims Manager Team

**Insurance Company Name :** NTUC Income Insurance Co-operative Ltd

**Accident Date and Time :** 14/07/2022 05:31 AM

**Vehicle Age(In Months) :** -

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

## Estimation Details

**Spare Part's Cost Detail**

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval					Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.6	Replace	✓	du
Standard	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Check	✓	?
Standard	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give	✓	?
Standard	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	1	0	Repair	✓	R
Standard	Main			BRACKET, FR BUMPER	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Give	✓	Xan
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	0	0	Not Give	✓	Xan
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	✓	Xan
Standard	Main			REINFORCEMENT FRONT UPPER	1	691.10	691.10	25.00	518.33	Replace	0	0	Check	✓	?
Standard	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0	Check	✓	?
Standard	Main			EXTENSION SUB-ASSY, LH	1	116.30	116.30	25.00	87.23	Replace	0	0	Not Give	✓	Xan
Standard	Main			EXTENSION SUB-ASSY, RH	1	116.30	116.30	25.00	87.23	Replace	0	0	Not Give	✓	Xan
Standard	Main			REINFORCEMENT FRONT LOWER	1	238.50	238.50	25.00	178.88	Replace	0	0	Not Give	✓	?
									Total Spare Part Cost	6,282.25	Surveyor Total				
									Lump Sum Discount (%)	20.00	Lump Sum Dis (%)				
									Final Spare Part Cost	5,025.80	Final Sur Total				

Standard BOM Type	Main Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			Remarks
				ABSORBER, FR BUMPER LOWER	Qty	List Price	List Price(\$)	Dis(%)	Final Price(\$)	Replace Repair/Replace	0 Surveyor Quantity	0 Surveyor Final Price(\$)	Check Repair/Replace	
Standard	Main			SEAL, HOOD TO FR END	1	24.40 Unit(\$)	24.40	25.00	18.30	Replace	0	0	Not Give	Xan
Standard	Main			EMBLEM ASSY FRONT	1	87.10	87.10	25.00	65.32	Replace	1	65.32	Replace	Xan
Standard	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0	Check	?
Standard	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0	Check	?
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	Xan
Standard	Main			RETAINER, FR BUMPER, LH & RH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give	Xan
Standard	Main			COVER ASSY, ENGINE	1	180.10	180.10	25.00	135.08	Replace	0	0	Not Give	Xan
Standard	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give	Xan
Standard	Main			UNIT , HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303	Replace	can
Standard	Main			COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	1	486.40	486.40	10.00	437.76	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A UPPER,	1	364.90	364.90	25.00	273.67	Replace	0	0	Not Give	Xan
Standard	Main			SUPPORT S/A RH	1	237.00	237.00	25.00	177.75	Replace	0	0	Not Give	Xan
Total Spare Part Cost									6,282.25	Surveyor Total			2,751.21	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20.00	
Final Spare Part Cost									5,025.80	Final Sur Total			2,200.97	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT PORTION	676.00	200.00	
Total:			676.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00	Xan
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00 <i>XM</i>	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	30.00	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 <i>XM</i>	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 <i>XM</i>	
Total:			380.00	30.00	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,025.80	2,200.97
Total Labour Cost	676.00	200.00
Total Spray Painting	558.00	200.00
Other	380.00	30.00
Overall Total	6,639.80	2,630.97
Lump Sum Repair Option	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	6,650.00	2,650.00
Surveyor Approved Amount		2,650.00
No of Repair Days*	4	3
Remarks	-	resurvey after repair lum sump
Surveyor Name		Rasul
Signature		
Survey Date	15/07/2022	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	15/07/2022 08:40 (SGT)
Reported by	Driver
Date of Accident	14/07/2022 13:31 (SGT)
Exact Location of Accident	Bukit Batok West Ave 6, Singapore
Additional Location Information	BUKIT BATOK WEST AVE 6 CAR PARK ENTRANCE
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5792J
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXX369K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

## INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-22099115MFSH

## DRIVER

Name of Driver	TAN CHIN HENG
NRIC No	SXXXX796C
Date Of Birth	01/02/1964
Occupation	Outdoor

Valid Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

19/09/1981  
40 YEARS AND 10 MONTHS  
Male  
(Phone) +65-68662672  
-  
Auto-Svcs-TARC@smrt.com.sg  
1  
-  
-  
No  
Hirer  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear  
Weather Conditions Clear  
Road Surface Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other vehicle or property damaged? Yes  
Number of Passengers (Including Driver) 1  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No  
Translator's name -  
Translator's ID -  
Translator's phone number -  
Translator's email -  
Original language used in the statement -

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

ON 14/07/22 AT ABOUT 1331HRS. I WAS TRAVELLING ALONG BUKIT BATOK WEST AVE 6. WHEN I REACHED BUKIT BATOK WEST AVE 6 CAR PARK ENTRANCE, A VEHICLE(SLE5131D) WHICH WAS IN FRONT OF MY VEHICLE STOPPED TO PICK UP PASSENGERS. AFTER THE PASSENGERS BOARDED, THE FRONT VEHICLE SUDDENLY REVERSED AND HIT ONTO THE RIGHT FRONT PORTION OF MY VEHICLE.

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLE5131D  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category -  
Private car

Name of Driver  
Contact Number  
Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
-  
-  
-

## IMPORTANT NOTICE

## SKETCH PLAN


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

### Sketch Plan



Describe Circumstance of the Accident

Declaration

We declare the foregoing particulars are true in every respect



Policy Code: 3524240 / Date & Time

Driver's Signature (for vehicle policy only) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NR(CO) card)

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5792J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8253623
Chassis No.:	JTDKB3FU203575925
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	11 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$14,513.00
Total Rebate Amount:	\$18,263.00
Message	

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jul 2022

OK