(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/CT/22006762/Ucy3

# ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMR 5993C

at Workshop m/s Kazen

of

Insured: GBF 441E

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value: $66k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted: LYA 34747

Veh No: SMR5993C Yr Regn: 18/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA

Make: KIA cerato k3 c.c 1591

Colour Blue A/C: Insured / Std / NI / NA

Sp.Reading 55529 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KNAFX411M J5755771

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or KUMHO

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 6 mm | R/Bal. | 6 mm |
| L/Bal. | 6 mm | L/Bal. | 6 mm |
| D.O.A. | 14/07/22 | D.O.I. | 18/07/22 |

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | Qn 11k. SMR5993C02051 |
| 5/8/22 | c/s @ $100 informed Shwan (Red $22,644.00 / 82%) |

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($ ) __S + RS.__SI

☐ : Interview ($ ) Photos

☐ : Tech. Invs ($ ) Others

☐ : Weekend ($ )

Report Format :

Lump Sum / I.B.I: ($ )

TOTAL