

ASS. REC. BY: Tajm

REF: CS/TM/22006774/Tcy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SU1A4293U Yr Regn: 2019, Oct
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai Lonig C.C. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 26276 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHC85/CVLU787147
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: ~ ~
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Wentlake
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 18/7/22
 Survey held at Compt byay
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S wing mirror
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

Report Format: _____
 Lump Sum / E.B. / % _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

MVA : Loke Wei Yiang

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/07/2022
Vehicle Reg. No.:	SHA4293U	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	25/10/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU399146	Chassis No:	KMHC851CVLU187147
Odometer:	262176 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	2		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,113.36
Miscellaneous Items	11.00
Labour	380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,504.36
+ GST 7.00% (S\$)	105.31
Nett Amount (S\$)	1,609.67

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jul 2022)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA4293U/15/07/2022 12:45	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR MIRROR LH	20.00	0.00	<i>buo</i> *1,391.70 FL
Sub Total (S\$)						1,391.70
- List Item Discount on L Items (S\$)						278.34
Total Parts (S\$)						1,113.36

ComfortDelGro Engineering Pte Ltd/SHA4293U/15/07/2022 12:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$)			<u>11.00</u>

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR CHARGES	New	175 200.00
2	SPRAY PAINTING	New	100 150.00
3	CHECK LIGHTING AND WIRING	New	✓ 30.00
Gross Labour Cost (\$)			<u>380.00</u>

ComfortDelGro Engineering Pte Ltd/SHA4293U/15/07/2022 12:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufik 97495749
 WP 18/7/22 @ 3pm
 r/p Resurvey before paint
 0/day
 Taufik@khantab.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: