

| | | | | | |
|--------------|-----------------|---------------|---------------|-----------|-------------------------------|
| Plate Number | Case Number | Brand | Model Details | Body Type | Insurance company |
| SMN3811D | MFL2022D0003656 | Nissan | Qashqai | SUV | India International Insurance |
| Technician | SA | Parts Manager | | | |
| - | LKK_assignments | - | | | |

No data

Remarks 2 remarks

Supp item review done base on survey information provided

Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Note: Align with LKK surveyor assessment, however labour and painting been adjusted, please refer as follow.

Supp items review by : Insurlogic

Parts : \$2319.30

2022-07-22 12:00 Assessor Supervisor-Insurlogic 4 42797773348

Pre review by insurlogic:

Parts : \$18174.60

Labour : \$2630.00

Total: \$20804.60

Repair days: 10

check item(before discount) : \$1673.00
