

ASSIGNMENT

From: PRS Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMA 770S Yr Regn: 29/10/19
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Volvo SE0 c.c. 1909
 Colour: Red A/C: Insured / Std / Nil / NA
 Sp. Reading: 30782 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JRZSIOACL6036757
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 235/45R18
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 15/7/22 D.O.I. 29/7/22
 Survey held at JSS SPRAY
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front RH
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

MI-160K
Repair range 1K - 5K
4 days

Date/Time, File Pass to?

☐ : Prell. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.H. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL