

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I	PTE LTD	R	Ref:	CS3/ASM22006791/Rqy3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		D	Date:	03/10/2022	
	ATTN: KHOR SAW	THENG	C	Code:	ASM	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 1120E	Veh. Inspected		SLH 5445H	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M046U6	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		18/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	LEXUS ES300H 4DR SEDAN (A)	c.c		2487	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTHB21B1102033672	Colour		WHITE	
	Odometer	114097 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/45 R18	MICHELIN		6 mm	
	L/H Front Tyre	235/45 R18	MICHELIN		6 mm	
	R/H Rear Tyre	235/45 R18	MICHELIN		6 mm	
	L/H Rear Tyre	235/45 R18	MICHELIN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.				
5.	5. General Information					
	Accident Date	16/07/2022	Inspect Date / Ti	me	19/07/2022 ( 12:37 PM )	
	Survey held at 10 Ang Mo Kio Industrial Park 2A #03-09/17					
	Repairer SZE KANG AUTOMOBILE SPRAYING SERVICES					
5a.						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22006791/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 ${\tt BEng(Hons),B.Bus,MBA,PEng,PE,\,MInstAEA,MASME,MIRTE}$ 

REGD Auto Consultant-SAE, Licensed Appraiser