08/11/0 wef
ASS. EC. BY: Rahmi

REF: CS3/ASM22006791/Ray3

063E

ASSIGNMENT

From : Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 5445H

at Workshop m/s SZE KANG AUTOMOBILE

of 10, AMK AUTOPOINT #03-09/17

Insured: ASM

Policy No.

Claim No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 124K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLH 5445H Yr Regn: 21/03/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: LEXUS ES300H 4DR SDN (A) c.c 2487

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 114697 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTHB21B110203367 2

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/45R18

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	16/07/22	D.O.I.	19/07/22

Survey held at SZE KANG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT -

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-3K) / 4 days

Date/Time, File Pass to? [ ] : Preli. Report

1) [ ] : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: [ ] : Site Insp ($) S + RS SI

[ ] : Interview ($) Photos

[ ] : Tech. Invs ($) Others

[ ] : Weekend ($)

TOTAL

Report Format :

Lump Sum / I.B.I: ($)