

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMD22006806/4243

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

459A
Vehicle: IN / OUT

Veh No:

FRJ81774

Yr Regn:

01/11/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KYMCO K-XCT200iC 199

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

— Damage.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RFBD82000E1000177

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70-14

R:

150/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Timsun

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

15/07/22

D.O.I.

1/8/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt, N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L1A \$991 NOT \$3509

11/8/22 have h.a
1/5 \$3200 informed Shawn (red \$6985.90, 692)

Date/Time, File Pass to?

1) 11/8/22

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / I.B.A. (\$

3200

TOTAL

IMPERIUM AUTOMOTIVE

25 Kaki Bukit Road 4 #01-47 Synergy@KB, Singapore 417800

HP : 9748 9940 Shawn Tan

Email: shawn7530@hotmail.com

Not Authorized

2 Aug 2022

Vehicle No.: FBJ 8177 U

*24k
11/8/22
1/s \$ 3200
4 days*

Model: Kymco K-XCT2001

QTY	DESCRIPTION	AMT S\$
	List Items	
1	Front fender <i>BPO</i>	\$ 185.00 ✓
2	Front side fork assy <i>SLC</i>	\$ 2,040.00 X
1	Fork under bracket <i>nn</i>	\$ 385.00 X
1	Front sport rim <i>nn</i>	\$ 350.00 X
1	Front brake disc <i>nn</i>	\$ 220.00 X
1	Front rim shaft <i>nn</i>	\$ 52.00 X
1	Windshield <i>SCR</i>	\$ 245.00 ✓
1	Headlamp assy -LH <i>SLC</i>	\$ 844.00 ✓
1	Side mirror assy -LH <i>cu7</i>	\$ 178.00 ✓
1	Handle bar <i>sent</i>	\$ 188.00 ✓
1	Handle bar balancer -LH <i>cu7</i>	\$ 80.00 ✓
1	Clutch lever <i>cu7</i>	\$ 78.00 ✓
1	Front signal -LH <i>SLC</i>	\$ 225.00 X
1	Centre inner panel handle <i>cre nlc</i>	\$ 150.00 X
1	Footstep panel -LH <i>cu7</i>	\$ 168.00 ✓
1	Rear footrest -LH <i>cu7</i>	\$ 55.00 ✓
1	Drove belt cover <i>cu7</i>	\$ 345.00 ✓
1	Drove belt outer garnish <i>cu7</i>	\$ 215.00 X
1	Air filter box cover <i>cu7</i>	\$ 250.00 ✓
1	Main stand <i>R</i>	\$ 145.00 X
1	Side stand <i>R</i>	\$ 95.00 X
1	Rear mudguard <i>nn</i>	\$ 148.00 X
1 set	fairing cover (1 set) <i>cu7/daye</i>	\$ 1,350.00 ✓
		\$ 7,991.00
	Less 10%	\$ 799.10
		\$ 7,191.90

*3363
107
3026.7*

Special Nett Items

1	Number plate (1 set)	11	\$	28.00	X
1	Rear box	cu7	\$	680.00	300
1	Rear box bracket	11	\$	150.00	X
2	Fork oils	11	\$	30.00	X
2	Fork oil seals	11	\$	56.00	X
1	Steering cone (1 set)	11	\$	185.00	X
1	"K-XCT" emblem	11	\$	55.00	
			\$	1,184.00	

S/N. Labour Charges

- To provide towing service.
- To check wiring and reset headlamp focusing
- To provide labour.
- To respray painting .

Grand Total : \$ 10,185.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), "during resurvey"
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: