



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006826/Kqy3q2	
			Date: 29/08/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBF 6912Z	Veh. Inspected	FBS 2797Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202440/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	19/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3SG5680MK058692	Colour	BLACK
	Odometer	40566 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R13	PIRELLI	3 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	PIRELLI	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/07/2022	Inspection Date	19/07/2022
	Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	