PRS Filed By: GQ REF: CS3/CTI22006845/Gvy3

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SUNRISE AUTO

of

Insured: SKV 39T

Policy No. DMPCSNW00085202201

Claims No. SNM22D204864/C02/LEEPG

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

	N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: $62k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SNA6540Y Yr Regn: 15 Jan/2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA WISH 1.8 c.c 1794

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 223987 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDER12W503001601 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm

D.O.A. 12/7/2022 D.O.I. 19-07-2022

Survey held at W/S 5:30PM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$3000 - $4000
4/8/22	Submit PRS, repair range $3,000-$4,000

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 4/8/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL

Report Format:

Lump Sum / LPO: